

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5125832185	Date of Loss:	13/12/2022
Vehicle Reg. No.:	SKC6050U	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SLF1032C
Any Injuries?	no	Contact No:	
Insured/Claimant:	NG KAI SAN	Driver:	NG KAI SAN

PARTS MODEL

Make/Model:	Toyota, Altis - MR053REE	Vehicle Reg. Date:	14/09/2011
Vehicle Colour:		Engine Number:	
Chassis No:	MR053REE104121975	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss CHAIN COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	11,060.23
Miscellaneous Items	430.00
Labour	4,040.00
Paintwork Labour	2,210.00
Towing	0.00
Gross Total(S\$):	17,740.23
GST 7.00%(S\$):	1,241.82
Nett Amount(S\$):	18,982.05

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>re</i>	756.47	624 ✓ -25.00	567.35
2	1	FRONT BUMPER SIDE RETAINER LH <i>? X nn</i>	58.00	-25.00	43.50
3	1	FRONT BUMPER SIDE RETAINER RH <i>? X nn</i>	58.00	-25.00	43.50
4	1	FRONT BUMPER BRACKET LH <i>? ✓ BR</i>	62.00	✓ -25.00	46.50
5	1	FRONT BUMPER BRACKET RH <i>? X nn</i>	62.00	-25.00	46.50
6	1	FRONT GRILLE <i>? ✓ BR</i>	486.70	381 ✓ -25.00	365.03
7	1	FRONT GRILLE LOGO <i>? NEC</i>	85.00	✓ -25.00	63.75
8	1	FRONT GRILLE CHROME MOULDING <i>? X nn</i>	294.80	-25.00	221.10
9	1	BONNET <i>BT</i>	1,100.00	796 ✓ -25.00	825.00
10	1	BONNET HINGES LH <i>BT</i>	160.00	✓ -25.00	120.00
11	1	BONNET HINGES RH <i>BT</i>	160.00	✓ -25.00	120.00
12	1	FRONT SUPPORT PANEL <i>? X Repair</i>	535.00	-25.00	401.25
13	1	FRONT BUMPER REINFORCEMENT <i>? X nn</i>	480.00	-25.00	360.00
14	1	FRONT FENDER LH <i>X ? BR</i>	330.00	-25.00	247.50
15	1	FRONT HEADLAMP LH <i>✓ BR</i>	650.00	✓ -25.00	487.50
16	1	FRONT HEADLAMP RH <i>BR</i>	650.00	✓ -25.00	487.50
17	1	REAR BUMPER <i>re</i>	710.00	482 ✓ -25.00	532.50
18	1	REAR BUMPER SIDE RETAINER LH <i>X L</i>	65.00	-25.00	48.75
19	1	REAR BUMPER SIDE RETAINER RH <i>X L</i>	65.00	-25.00	48.75
20	1	REAR BUMPER BRACKET LH <i>? ✓ BR</i>	75.00	✓ -25.00	56.25
21	1	REAR BUMPER BRACKET RH <i>? ✓ BR</i>	75.00	✓ -25.00	56.25
22	1	REAR BUMPER REINFORCEMENT <i>? ✓ BT</i>	380.00	✓ -25.00	285.00
23	1	REAR BUMPER REFLECTOR LH <i>X L</i>	110.00	-25.00	82.50
24	1	REAR BUMPER REFLECTOR RH <i>X L</i>	110.00	-25.00	82.50
25	1	REAR BOOT LID <i>BT</i>	780.00	✓ -25.00	585.00
26	1	REAR BOOT LID HINGES LH <i>X L</i>	170.00	-25.00	127.50
27	1	REAR BOOT LID HINGES RH <i>X L</i>	170.00	-25.00	127.50
28	1	REAR BOOT LID LOGO <i>re</i>	68.00	✓ -25.00	51.00
29	1	REAR BOOT LID COROLLA EMBLEM <i>re</i>	55.00	✓ -25.00	41.25
30	1	REAR BOOT LID ALTIS EMBLEM <i>re</i>	58.00	✓ -25.00	43.50
31	1	REAR BOOT LID VVTI EMBLEM <i>re</i>	55.00	✓ -25.00	41.25
32	1	REAR BOOT LID DUAL EMBLEM <i>re</i>	60.00	✓ -25.00	45.00
33	1	REAR BOOT LID 1.6 EMBLEM <i>re</i>	58.00	✓ -25.00	43.50
34	1	REAR BOOT LID REFLECTOR LH <i>X nn</i>	170.00	-25.00	127.50
35	1	REAR BOOT LID REFLECTOR RH <i>cut</i>	170.00	✓ -25.00	127.50
36	1	REAR BOOT LID OUTER CHROME MOULDING <i>X nn</i>	310.00	-25.00	232.50
37	1	REAR BOOT LID LOCK <i>cut</i>	430.00	✓ -25.00	322.50
38	1	REAR BOOT LID LOCK CATCH <i>X nn</i>	120.00	-25.00	90.00
39	1	REAR TAILLAMP RH <i>cut</i>	455.00	✓ -25.00	341.25
40	1	REAR TAILLAMP PANEL RH <i>? X repair</i>	480.00	-25.00	360.00
41	1	REAR END PANEL <i>? ✓ DD</i>	980.00	590 ✓ -25.00	735.00
42	1	REAR END PANEL TOP GARNISH <i>re</i>	270.00	184 ✓ -25.00	202.50
43	1	REAR FENDER RH <i>X repair</i>	1,250.00	-25.00	937.50
44	1	REAR SPARE TYRE PANEL <i>? X nn</i>	870.00	-25.00	652.50
45	1	REAR SPARE TYRE BOARD <i>? X nn</i>	250.00	-25.00	187.50
			7543 -25% 5657.25	Total Parts (S\$)	11,060.23

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE <i>BT</i>	45.00	0.00	45.00 ✓

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc	
2	1	FRONT BUMPER CLIPS (1 SET) <i>MC</i>	40.00	0.00	40.00	30 ✓
3	1	REAR NUMBER PLATE <i>X MC</i>	45.00	0.00	45.00	
4	1	REAR BUMPER SENSORS (SET) <i>7 Shorted</i>	260.00	0.00	260.00	200 ✓
5	1	REAR BUMPER CLIPS (SET) <i>MC</i>	40.00	0.00	40.00	30 ✓
			305 Sub Total (\$\$)		430.00	

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	60.00	0.00	60.00	30
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00	40
3	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00	60
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	3,800.00	0.00	3,800.00	800
			Gross Labour Cost (\$\$)		4,040.00	

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Supply Spray Terostat Sealant On The Cutting Areas.	70.00	0.00	70.00	30 ✓
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00	30 ✓
3	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00	X
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	2,000.00	0.00	2,000.00	1200
					2190	
			Gross Labour Cost (\$\$)		2,210.00	

< END OF ESTIMATES >

8152.25

L/S - 6521.80
= 6500

7 Days.

Company Name

After repair photos

Gmo @ 100
8288 0282

22/12/22

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- All supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Approved by Repairer