

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22012758/Rny3e2
	8 SHENTON WAY AXA TOWERSING		Date:	28/12/2022	
	ATTN: ANG YVON	NE		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3194M	Veh. Inspected		FBL 2891U
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M04FKV	Excess (\$)		0.00
	Assign From	ANG YVONNE	Assign Date		21/12/2022
2.	Vehicle Particulars & Condition				
	Make & Model	SUZUKI UH200AL6 BURGMAN	c.c		200
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	MLCC91121G0402786	Colour		BLACK
	Odometer	43789 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	110/90-13	MICHELIN		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	130/70-12	MICHELIN		4 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR PORTION.			₹	
5.	General Information				
	Accident Date	27/11/2022	Inspect Date / 1	Γime	21/12/2022 ( 01:06 PM )
	Survey held at FUTURE SCOOTERING				
	50 BUKIT BATOK STREET 23 #02-2627 MIDVIEW BUILDING SINGAPORE 659578				
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22012758/Rny3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser