

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 9371K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	N/S REAR DOOR OUTER MOULDING	BENT	85.00	85.00
1	N/S REAR DOOR WEATHERSTRIP	NOT NECESSARY	225.00	-
1	N/S REAR DOOR LOCK	NOT NECESSARY	250.00	-
1	N/S REAR DOOR	BADLY DENTED	1,250.70	971.20
1	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	45.00	-
1	N/S REAR DOOR WEATHERSTRIP LOWER	NECESSARY	35.00	35.00
1	N/S REAR DOOR WEATHERSTRIP FRONT	CUT	35.00	35.00
1	N/S REAR DOOR VERTICAL STICKER	NECESSARY	80.00	80.00
1	N/S REAR FENDER OUTER PROTECTOR	GRAZED	180.20	180.20
1	N/S REAR DOOR REGULATOR WITH POWER WINDOW MOTOR	BENT/JAMMED	305.40	305.40
1	N/S REAR DOOR INNER TRIMBOARD	NOT NECESSARY	445.80	-
	LESS 20% DISCOUNT		-587.42	-338.36
			2,349.68	1,353.44
	<u>LABOUR</u>			
	TO RUST-PROOFING OF THE AFFECTED AREAS.		100.00	30.00
	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.		100.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	80.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		900.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	550.00
			1,980.00	940.00
	GRAND TOTAL		4,329.68	2,293.44

RECOMMENDED COST OF LUMP SUM REPAIRS		1,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22012764/Uny3m4

CHUA KANG SENG

Licensed Appraiser