

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R | | | | | |
|---|---|--|-----------------|-------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | F | Ref: | CS/AGI22012764/Uny3m4 | |
| | (BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924 | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | [| Date: | 04/01/2023 | |
| | | | (| Code: | AGI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SMD 7963A | Veh. Inspected | | SMT 9371K | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | C10019411/JL | Excess (\$) | | 0.00 | |
| | Assign From | FRAULEINE KHOO | Assign Date | | 21/12/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA VEZEL (A) | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2020 | |
| | Chassis No. | RU11329041 | Colour | | BLUE | |
| | Odometer | 38013 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R16 | DUNLOP | | 7 mm | |
| | L/H Front Tyre | 215/60 R16 | DUNLOP | | 7 mm | |
| | R/H Rear Tyre | 215/60 R16 | DUNLOP | | 7 mm | |
| | L/H Rear Tyre | 215/60 R16 | DUNLOP | | 7 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 20/12/2022 | Inspection Date | ! | 22/12/2022 | |
| | Survey held at | TAN LIM MOTOR PTE LTD | | | | |
| | | NO.1 DEFU LANE 6 SINGAPORE 539365 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: