

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22012767/RQY3E2**Date:** 18/01/2023**REFERENCE**

Insured/Claimant:	WU JIANWEI	Policy No:	7210114406		
Date of Loss:	29/06/2022	Nature of Claim:	OD	Claim No:	2543683405SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLF8283Z</b>		Engine No:	HIDDEN
Make & Model:	AUDI RS, E-TRON GT (A)		Chassis No:	WAUZZZFW7N7902024
Reg. Date:	24/09/2021 (Man. Year: 2021)		Odometer:	0 km
Colour:	Black			
Engine Capacity:	0 cc			
Market Value/New Car Price:	S\$517,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	305/30 R21	Rear Tyre Size:	305/30 R21
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	2,000.00	2,000.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>-2,000.00</b>	<b>-2,000.00</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment:	22/12/2022		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	29/11/2022	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	0.0 days		

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$517,000.00
OMV :	\$129,703.00
PARF Rebate (1) :	\$120,349.00
Quota Premium Paid :	\$59,501.00
COE Rebate (2) :	\$52,079.00
Total Rebate (1) + (2) = :	\$172,428.00

The total amount incurred will be Market Value \$517,000.00 minus Total Rebate \$172,428.00 = \$344,572 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >