

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III22008734/RQY3E2-1**Date:** 31/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SLE7186H **Insured Vehicle No :** SLT4120M
 Date of Loss: 31/08/2022 Nature of Claim: TP Claim No: MFL2022D0005018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE7186H**
 Make & Model: FORD KUGA, 1.5 Titanium (A) Engine No: GG60320
 Reg. Date: 29/07/2016 (Man. Year: 2016) Chassis No: WF0AXXWPMAGG60320
 Colour: Brown Odometer: 93117 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,285.60	4,162.64	3,122.96	42.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	780.00	1,280.00	62.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,345.60	4,942.64	4,402.96	47.11
Approved Total (Overridden) (S\$)		3,950.00		
Nett Amount (S\$)	9,345.60	3,950.00	5,395.60	57.73

INSPECTION

Date of Assignment: 20/12/2022
 Date Inspected: 19/09/2022 Inspected At: King's Auto Repair & Service Pte Ltd (HQ)
 Estimated Period of Repair: 4.0 days BLK 176 SIN MING DRIVE, #02-10
 Singapore 575721

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	M1-SUV	FORD KUGA 1.5 Titanium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE7186H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Broken	1,709.00 FL	*1,650.00 FL
2	1		*FRONT BUMPER LH CORNER PARKING SENSOR	Broken / Malfunction	185.00 FL	*185.00 FL
3	1		*FRONT BUMPER LH FOG LAMP	Serviceable	310.00 FL	*- FL
4	1		*FRONT BUMPER LH FOG LAMP TOP COVER	Cut / Grazed	170.00 FL	*170.00 FL
5	1		*FRONT BUMPER LH SIDE RETAINER	Serviceable	100.00 FL	*- FL
6	1		*FRONT BUMPER INNER REINFORCEMENT	Serviceable	590.00 FL	*- FL
7	1		*SET FRONT BUMPER CLIPS	Broken / Necessary	50.00 FL	*50.00 FL
8	1		*LH HEADLAMP	Broken / Cut	3,940.00 FL	*2,280.00 FL
9	1		*LH HEADLAMP WASHER NOZZLE COVER	Broken / Missing	110.00 FL	*110.00 FL
10	1		*LH HEADLAMP WASHER NOZZLE	Bent / Jammed	545.00 FL	*545.00 FL
11	1		*LH HEADLAMP WASHER NOZZLE BRACKET	Serviceable	113.00 FL	*- FL
12	1		*FRONT LH FENDER	Repair	685.00 FL	*- FL
13	1		*FRONT LH FENDER UNDER BLACK PROTECTOR	Broken / Deformed	415.00 FL	*213.30 FL
14	1		*SET FRONT LH FENDER UNDER BLACK PROTECTOR PARKING SENSOR	Serviceable	185.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,107.00	5,203.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,821.40	1,040.66
Total Parts (\$\$)	7,285.60	4,162.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS	New	800.00	300.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,000.00	400.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	50.00	30.00
4	TO REMOVE, REFIX & RESET FRONT BUMPER PARKING SENSORS	New	80.00	50.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	0.00
6	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS	New	50.00	0.00
Gross Labour Cost (\$\$)			2,060.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >