

AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS

Leow Peck San Sandy
C/O King's Auto Repair & Service Pte Ltd
176 Sin Ming Drive
Sin Ming AutoCare #02-10
Singapore 575721

1 Reference

Job Reference No : 22/002572
Claim No : -
Claim Type : Third Party
Accident Date : 31/08/2022
Survey Date : 20/09/2022
Survey Report Date : 18/11/2022

2 Particulars Of Vehicle

Vehicle Registration No : SLE7186H
Make & Model : Ford Kuga Titanium 1.5 GDI
Vehicle Registration Date : 29/07/2016
Chassis No : WF0AXXWPMAGG60320
Engine No : Blocked
Colour : Orange

3 Condition Of Vehicle And Tyres

| <u>Mileage (KM)</u> | <u>Brakes</u> | <u>Steering</u> | <u>Modification</u> |
|---------------------|---------------|-----------------|---------------------|
| 93117 | Serviceable | Serviceable | None |
| <u>Tyres</u> | <u>Make</u> | <u>Size</u> | <u>Balance (MM)</u> |
| Front RHS | Michelin | 235/50R18 | 5 |
| Front LHS | Michelin | 235/50R18 | 5 |
| Rear RHS | Michelin | 235/50R18 | 6 |
| Rear LHS | Michelin | 235/50R18 | 6 |

4 Description Of Damages

The vehicle sustained damages at front left hand portion.
(For information of damages please refer to Parts/Labour/Photographs attached)

5 Instruction

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex A

Ref No : 22/002572

Damage And Repair Cost Adjustment

| S/No | Qty | Parts Description | Comments/condition | Workshop Estimate (\$) | Our Assessment (\$) |
|---------------------|-------|--|--------------------|------------------------|--------------------------|
| | | | <u>List Items</u> | | |
| 1 | 1 | Front bumper | Deformed/broken | 1,709.00 | 1,709.00 1650 |
| 2 | 1 | Front bumper LH corner parking sensor | Broken/malfunction | 185.00 | 185.00 ✓ |
| 3 | 1 | Front bumper LH fog lamp XSV | Broken/cut | 310.00 | 310.00 X |
| 4 | 1 | Front bumper LH fog lamp top cover | Cut/grazed | 170.00 | 170.00 ✓ |
| 5 | 1 | Front bumper LH side retainer XSV | Deformed | 100.00 | 100.00 X |
| 6 | 1 | Front bumper inner reinforcement | Serviceable/reuse | 590.00 | - |
| 7 | 1 set | Front bumper clips | Broken/necessary | 50.00 | 50.00 ✓ |
| 8 | 1 | LH headlamp | Broken/cut | 3,940.00 | 3,940.00 2280 |
| 9 | 1 | LH headlamp washer nozzle cover | Broken/missing | 110.00 | 110.00 ✓ |
| 10 | 1 | LH headlamp washer nozzle | Bent/jammed | 545.00 | 545.00 ✓ |
| 11 | 1 | LH headlamp washer nozzle bracket XSV | Broken/deformed | 113.00 | 113.00 X |
| 12 | 1 | Front LH fender | To repair | 685.00 | - |
| 13 | 1 | Front LH fender under black protector | Broken/deformed | 415.00 | 415.00 213.30 |
| 14 | 1 set | Front LH fender under black protector parking sensor XSV | Malfunction | 185.00 | 185.00 X |
| | | | 5203.30 | | |
| | | | 20% | | |
| | | | 4162.64 | | |
| Less discount 20% | | | | | |
| | | | Total : | 9,107.00 | 7,832.00 |
| | | | | 1,821.40 | 1,566.40 |
| | | | | 7,285.60 | 6,265.60 |
| Total Spare Parts : | | | | 7,285.60 | 6,265.60 |

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 22/002572

Damage And Repair Cost Adjustment

| <u>Items</u> | <u>Job Description</u> | <u>Workshop Estimate (\$)</u> | <u>Adjusted Costs (\$)</u> |
|----------------------|---|-------------------------------|----------------------------|
| 1 | To remove, jack out, straighten, panel beating, align and renew replaced parts. | 800.00 | 500.00 300 |
| 2 | To putty and respray painting on affected areas. | 1,000.00 | 600.00 400 |
| 3 | To check wirings and lightings. | 50.00 | 30.00 ✓ |
| 4 | To remove, refix & reset front bumper parking sensors. | 80.00 | 50.00 ✓ |
| 5 | To conduct computerise wheel alignment test. | 80.00 | 60.00 X 17 |
| 6 | To supplied and applied anti rust treatments. | 50.00 | 30.00 X 12 |
| Total Labour : | | 2,060.00 | 1,270.00 |
| Total Spare Parts : | | 7,285.60 | 6,265.60 |
| Total Labour : | | 2,060.00 | 1,270.00 |
| Total Repair Costs : | | 9,345.60 | 7,535.60 |

Assessor's Recommendation

Repairer Estimate : 9,345.60
 Our Adjustment : 7,535.60

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,000.00, with a repair period of 4 working days.

Surveyed By:

Lek Boon Hwee
 Automobile Appraiser

4162.64

780.00

4942.64

20%

3954.11

48-\$3,950 / 4 days