

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22012782/UWY3M4**Date:** 20/01/2023**REFERENCE**

Insured/Claimant: DP PLUMBING & SANITARY
SERVICE PTE LTD

Policy No: DMCVSNW00117642202

Date of Loss: 21/12/2022

Nature of
Claim: ODClaim
No: SNM22D209170/C01/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBK6644X**

Make & Model: TOYOTA DYNA, 3.0 D (M)

Engine No: 1KDB039567

Reg. Date: 12/10/2020 (Man. Year: 2020)

Chassis No: KDY2318042847

Colour: White

Odometer: 119229 km

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$86,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R13 (D/D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,485.00	1,455.00	30.00	2.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,108.99	809.62	299.37	26.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,593.99	2,264.62	329.37	12.70
Approved Total (Overridden) (S\$)		1,800.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	2,593.99	1,300.00	1,293.99	49.88
+ GST 7.00/7.00% (S\$)	181.58	91.00	90.58	49.88
Nett Amount (S\$)	2,775.57	1,391.00	1,384.57	49.88

INSPECTION

Date of Assignment: 22/12/2022 Present Location:

Car City Auto Centre Pte Ltd (HQ)

Date Inspected: 22/12/2022 Inspected At:

Car City Auto Centre Pte Ltd (HQ)
Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jan 2023)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK6644X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		1,485.00 F	*1,455.00 F
F=Franchise part.						
				Total Parts (S\$)	1,485.00	1,455.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	596.40	508.20
2	SPRAY PAINTING	New	512.59	301.42
Gross Labour Cost (S\$)			1,108.99	809.62

Report was unsubmitted during this print-out.

< END OF ESTIMATES >