



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3305P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT R/H DOOR WIND MIRROR ASSY	TO REPAIR SEE LABOUR	1,044.60	-
1	FRONT R/H DOOR ASSY	TO REPAIR SEE LABOUR	1,434.50	-
1	FRONT R/H DOOR OUTER HANDLE	NOT NECESSARY	293.80	-
1	FRONT R/H DOOR LOCK	NOT NECESSARY	455.60	-
1	FRONT R/H DOOR REGULATOR ASSY	NOT NECESSARY	565.50	-
1	FRONT R/H DOOR WEATHERSTRIP	NOT NECESSARY	187.60	-
2	FRONT R/H DOOR HINGES	NOT NECESSARY	91.60	-
1	FRONT R/H DOOR CHECKER	NOT NECESSARY	78.50	-
1	FRONT R/H DOOR BLACK STICKER	NOT NECESSARY	75.60	-
1	REAR R/H DOOR ASSY	DENTED	1,356.70	961.00
1	REAR R/H DOOR HINGES	NOT NECESSARY	91.60	-
1	REAR R/H DOOR CHECKER	NOT NECESSARY	78.50	-
1	REAR R/H DOOR LOCK ASSY	DAMAGED	315.40	245.00
1	REAR R/H DOOR WEATHERSTRIP	NOT NECESSARY	187.60	-
1	REAR R/H DOOR BLACK STICKER	NECESSARY	75.60	75.60
1	REAR R/H WHEEL ARCH GARNISH	CUT	300.70	195.00
1	R/H SIDE SILL GARNISH ASSY (CENTRE LOWER)	NOT NECESSARY	688.80	-
1	REAR R/H FENDER ASSY	TO REPAIR SEE LABOUR	1,500.70	-
1	CENTRE DOOR PILLAR	NOT NECESSARY	998.70	-
	LESS 15% DISCOUNT		-1,473.24	-
	LESS 20% DISCOUNT		-	-295.32
			8,348.36	1,181.28
	<u>LABOUR</u>			
	TO DISM / REWIRE DAMAGED PORTION.		250.00	30.00
	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS. INCLUSIVE OF THE REPAIR OF FRONT R/H DOOR WIND MIRROR ASSY, FRONT R/H DOOR ASSY AND REAR R/H FENDER ASSY.		1,300.00	400.00
	TO PUTTY AND RESPRAY DAMAGED PORTION.		1,200.00	700.00

Report Ref No. CS/SMO22012784/Aqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISM / REFIX SEAT / PILLAR GARNISH / FLOOR MAT IN REPAIR.		200.00	40.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO DISM / REFIX REAR R/H FENDER GLASS IN REPAIR.	NOT NECESSARY	80.00	-
	TO SPRAY UNDERCOATING IN REPAIR.		150.00	50.00
			3,300.00	1,220.00
GRAND TOTAL			11,648.36	2,401.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/SMO22012784/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.