

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS22012786/TWY3E2**Date:** 12/05/2023**REFERENCE**

Insured/Claimant:	BIS MOTORING PTE LTD	Policy No:	SP2002451400
Date of Loss:	20/12/2022	Nature of Claim:	OD
		Claim No:	202222009048/JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML7704P		
Make & Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A)	Engine No:	A2183328JSUX0428
Reg. Date:	03/06/2019 (Man. Year: 2019)	Chassis No:	W0VZM6EF0K1035006
Colour:	Black	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$96,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Luxxan 7 mm	Rear Left Side:	Vinmax 7 mm
Front Right Side:	Luxxan 7 mm	Rear Right Side:	Vinmax 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,772.40	4,654.10	5,118.30	52.38
Miscellaneous Items	164.00	75.00	89.00	54.27
Labour	2,440.00	1,090.00	1,350.00	55.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,376.40	5,819.10	6,557.30	52.98
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	10,376.40	3,819.10	6,557.30	63.19
+ GST 7.00/8.00% (S\$)	726.35	305.53	420.82	57.94
Nett Amount (S\$)	11,102.75	4,124.63	6,978.12	62.85

INSPECTION

Date of Assignment:	22/12/2022	Present Location:	Premier Automotive Services Pte Ltd (HQ)
Date Inspected:	27/12/2022	Inspected At:	Premier Automotive Services Pte Ltd (HQ)
			60 Jalan Lam Huat Carros Centre, #07-43
			Singapore 737869
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2023)
Parts:	143	OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML7704P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	39214206	*FRONT BONNET (WCP)	Bent	1,705.00 F	*1,705.00 F
2	1	39118540	*FRONT BONNET LOCK (WCP)	Not Necessary	43.00 F	*- F
3	1	39143307	*FRONT BONNET LOCK BRACKET (WCP)	Not Necessary	127.00 F	*- F
4	1	39126608	*FRONT BONNET HINGE LH (WCP)	Not Necessary	133.00 F	*- F
5	1	39126609	*FRONT BONNET HINGE RH (WCP)	Not Necessary	133.00 F	*- F
6	1	39150008	*FRONT BONNET DAMPER LH (WCP)	Not Necessary	125.00 F	*- F
7	1	39150008	*FRONT BONNET DAMPER RH (WCP)	Not Necessary	125.00 F	*- F
8	1	39107929	*FRONT RADIATOR GRILLE (WCP)	Cracked	299.00 F	*299.00 F
9	1	13491196	*FRONT RADIATOR GRILLE MOULDING (CHROME) (WCP)	Cracked	274.00 F	*390.00 F
10	1	13491190	*FRONT RADIATOR GRILLE MOULDING LH (CHROME) (WCP)	Cracked	131.00 F	*131.00 F
11	1	13491191	*FRONT RADIATOR GRILLE MOULDING RH (CHROME) (WCP)	Cracked	131.00 F	*131.00 F
12	1	39197502	*FRONT BUMPER UPPER INNER GARNISH (WCP)	Not Necessary	141.00 F	*- F
13	1	39114984	*FRONT RADIATOR TOP GARNISH (WCP)	Not Necessary	40.00 F	*- F
14	1	13491204	*FRONT LOGO EMBLEM (WCP)	Necessary	75.00 F	*75.00 F
15	1	39159651	*FRONT BUMPER (WCP)	Deformed	1,158.00 F	*1,158.00 F
16	1	39098178	*FRONT BUMPER SPONGE (WCP)	Not Necessary	107.00 F	*- F
17	1	39117745	*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	459.00 F	*- F
18	1	39108221	*FRONT BUMPER LOWER GRILLE (WCP)	Not Necessary	120.00 F	*- F
19	1	39108219	*FRONT BUMPER LOWER LIP GARNISH LH (WCP)	Not Necessary	62.00 F	*- F
20	1	39108220	*FRONT BUMPER LOWER LIP GARNISH RH (WCP)	Not Necessary	62.00 F	*- F
21	1	13491269	*INSERT, CHROME, FRONT FOGLAMP LH (WCP)	Not Necessary	537.00 F	*- F
22	1	13491272	*INSERT, CHROME, FRONT FOGLAMP RH (WCP)	Not Necessary	537.00 F	*- F
23	1	39210100	*FRONT HEADLAMP RH (WCP)	Not Necessary	822.00 F	*- F
24	1	13491383	*HEADLAMP BRACKET RH (WCP)	Cracked	47.00 F	*47.00 F
25	1	39077621	*FRONT UPPER SUPPORT PANEL (WCP)	Bent	170.00 F	*170.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	39143306	*FRONT SUPPORT PANEL (WCP)	Not Necessary	258.00 F	*- F
27	3	95515167	*FRONT PARKING SENSOR (WCP)	Not Necessary	615.00 F	*- F
28	1		*FRONT BUMPER WIRING HARDNESS (WCP)	Not Necessary	323.00 F	*- F
Supplementary #1						
29	1	39114984	*TOP RADIATOR GRILLE COVER (WCP)	Cracked	30.00 F	*30.00 F
30	1	84262659	*AIR DUCT (WCP)	Deformed	95.00 F	*95.00 F
F=Franchise part.						
					Sub Total (\$\$)	8,884.00 4,231.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	888.40 423.10
					Total Parts (\$\$)	9,772.40 4,654.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIP (7PCS) (NECESSARY)	49.00	30.00
2	1	LICENSE PLATE WITH CASING (BENT)	45.00	45.00
3	10	RADIATOR TOP COVER CLIP SET (NOT NECESSARY)	70.00	0.00
Sub Total (S\$)			164.00	75.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REFIX FRONT ACCIDENT POTION ,FRONT BONNET ,FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL AND ETC	New	1,200.00	500.00
2	TO DISMANTLE & RENEW FRONT PARKING SENSOR	New	120.00	40.00
3	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION INCLUDING ADJUST OF HEADLAMP	New	120.00	50.00
4	TO RESPRAY FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, AND ETC	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,440.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >