

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 9933U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEEP CUT/TORN	1,035.20	1,035.20
1	FRONT BUMPER SIDE RETAINER O/S	BENT/CRACKED	66.80	66.80
1	FRONT BUMPER FOG LAMP O/S	NOT NECESSARY	322.59	-
1	FRONT BUMPER FOG LAMP CHROME O/S	NOT NECESSARY	122.30	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	HEADLAMP ASSY O/S	HOLDER CRACKED	3,702.20	3,702.20
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	681.20	-
1	FRONT SPORT RIM 17 INCH O/S	WARPED	2,721.00	2,721.00
1	FRONT KNUCKLE ARM O/S	NOT NECESSARY	605.30	-
1	FRONT KNUCKLE ARM BEARING O/S	NOT NECESSARY	335.00	-
1	FRONT LOWER ARM O/S	NOT NECESSARY	619.10	-
	LESS 10% DISCOUNT		-1,026.07	-757.52
			9,234.62	6,817.68
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX FRONT PDC SENSOR.	NOT NECESSARY	80.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL REALIGNMENT.		120.00	60.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S.		680.00	400.00
	TO PUTTY & SPRAY PAINTING.		800.00	500.00
			1,960.00	980.00
	GRAND TOTAL		11,194.62	7,797.68

RECOMMENDED COST OF LUMP SUM REPAIRS		6,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP22012787/Uwy3m4

CHUA KANG SENG

Licensed Appraiser