6/30/23, 5:09 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI22012793/KQY3Q2
3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 **Date:** 30/06/2023

REFERENCE

Insured/Claimant: Ryan Xinwei Tan Policy No: DMPSNW00265742100

Date of Loss: 13/12/2022 Nature of Claim: OD Claim No: SNM22D208970/C01/CHNGPW

Engine No:

G227H465B48A20A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNA3717A

Make & Model: MINI COOPER S, 2.0 5DR FWD LED ABS NAV

(A)

Reg. Date: 21/07/2017 (Man. Year: 2017) Chassis No: WMWXS720602E46740

Colour: Metallic Pearl Pink Odometer: 66268 km

Engine Capacity: 1998 cc

Market Value/New Car Price:

S\$92,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/40 R18 Rear Tyre Size: 205/40 R18
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm
Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,659.75	9,118.70	3,541.05	27.97
Miscellaneous Items	485.00	230.00	255.00	52.58
Labour	584.50	801.50	-217.00	-37.13
Paintwork Labour	498.56	493.54	5.02	1.01
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,227.81	10,643.74	3,584.07	25.19
Approved Total (Overridden) (S\$)		8,500.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	14,227.81	8,250.00	5,977.81	42.01
+ GST 7.00/8.00% (S\$)	995.95	660.00	335.95	33.73
Nett Amount (S\$)	15,223.76	8,910.00	6,313.76	41.47

INSPECTION

Date of Assignment: 22/12/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 29/12/2022 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/30/23, 5:09 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jun 2023)

Parts: 144 MINI COOPER S 2.0 5DR FWD LED ABS NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNA3717A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*Parts		12,659.75 F	*9,118.70 F
т – папользе рак.		Total Parts (S\$)	12,659.75	9,118.70
	Repo	rt was unsubmitted during this print-out		

Gross Labour Cost (S\$)

1,083.06

1,295.04

Recommended Miscellaneous Items

No	Qty Particulars		Repairer's	Amount
Misc	cellaneous Items			
1	1 misc		485.00	230.00
		Sub Total (S\$)	485.00	230.00
Re	ecommended Labour			
No	Particulars	Lab.Type	Repairer's	Amount
<u>Pair</u>	ntwork Labour			
1	labour for paintworks	New	498.56	493.54
Lab	our Items			
2	labour for panel/mechanical	New	584.50	801.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >