

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012794/GQY3M4**Date:** 02/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00161362202	
Claimant Vehicle No :	SMC4187Z	Insured Vehicle No :	SLK9140U	
Date of Loss:	19/12/2022	Nature of Claim:	TP	Claim No: SNM22D209120/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC4187Z		Engine No:	MR20906942A
Make & Model:	NISSAN TEANA, 2.0 (A)		Chassis No:	JN1BDUJ32Z0001485
Reg. Date:	02/03/2010 (Man. Year: 2009)		Odometer:	227577 km
Colour:	Maroon			
Engine Capacity:	1997 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,527.41	1,314.45	4,212.96	76.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	1,070.00	410.00	27.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,007.41	2,384.45	4,622.96	65.97
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	7,007.41	1,900.00	5,107.41	72.89
+ GST 8.00/8.00% (S\$)	560.59	152.00	408.59	72.89
Nett Amount (S\$)	7,568.00	2,052.00	5,516.00	72.89

INSPECTION

Date of Assignment:	22/12/2022	
Date Inspected:	23/12/2022	Inspected At: Dickson Auto Care Centre Pte Ltd (HQ) 29 Ubi Road 4, Dickson Auto Centre Singapore 408619
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2023)
Parts:	143	NISSAN TEANA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC4187Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,026.60 F	*935.00 FL
2	2		*REAR BUMPER CHROME MOULDING LH & RH	Not Necessary	358.20 F	*- FL
3	2		*REAR BUMPER SIDE RETAINER LH & RH	Not Necessary	118.60 F	*- FL
4	1		*REAR BUMPER SENSOR	Not Necessary	350.00 F	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	406.60 F	*- FL
6	1		*REAR BUMPER SPONGE	Not Necessary	171.70 F	*- FL
7	1		*REAR BOOT	Repair	1,231.80 F	*- FL
8	1		*REAR BOOT INNER LOCK	Cut	135.50 F	*135.50 FL
9	1		*REAR BOOT LOGO	Necessary	85.10 F	*85.10 FL
10	1		*REAR BOOT TEANNA LOGO	Necessary	114.30 F	*114.30 FL
11	1		*REAR BOOT 250XL LOGO	Necessary	105.50 F	*105.50 FL
12	1		*REAR BOOT V6 LOGO	Necessary	85.10 F	*85.10 FL
13	1		*REAR BOOT NO PLATE UPPER CHROME MOULDING	Not Necessary	425.41 F	*- FL
14	1		*REAR BOOT NO PLATE LOWER CHROME MOULDING	Not Necessary	307.80 F	*- FL
15	1		*REAR END PANEL	Necessary	605.20 F	*- FL
					Sub Total (\$\$)	5,527.41 1,460.50
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 146.05
					Total Parts (\$\$)	5,527.41 1,314.45

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REVERSE SENSORS	New	200.00	40.00
2	TO REMOVE & REFIT TAIL LAMP, ELECTRICAL WIRING & TEST FOR PROPER FUNCTIONING	New	80.00	30.00
3	TO PROVIDE SKILL LABOUR TO REMOVE ALL REAR DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY & REALIGN	New	600.00	400.00
4	TO PROVIDE SKILL LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	New	600.00	600.00
Gross Labour Cost (S\$)			1,480.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >