

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI22012798/UQY3Q2**Date:** 19/01/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22008975
<b>Claimant Vehicle No :</b>	YP327C	<b>Insured Vehicle No :</b>	GBG2880C
Date of Loss:	21/12/2022	Nature of Claim:	TP
		Claim No:	CDMCG22002755

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YP327C</b>		
Make & Model:	HINO XZU710R, 4.0 D 14FT WID CAB 5T (A)	Engine No:	N04CUS24731
Reg. Date:	30/11/2015 (Man. Year: 2015)	Chassis No:	JHHUCS3H30K014983
Colour:	White	Odometer:	325206 km
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6/6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,100.00	2,960.50	7,139.50	70.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,220.00	1,900.00	60.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,220.00</b>	<b>4,180.50</b>	<b>9,039.50</b>	<b>68.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,300.00</b>		
<b>(S\$)</b>	13,220.00	3,300.00	9,920.00	75.04
<b>+ GST 8.00/8.00% (S\$)</b>	1,057.60	264.00	793.60	75.04
<b>Nett Amount (S\$)</b>	<b>14,277.60</b>	<b>3,564.00</b>	<b>10,713.60</b>	<b>75.04</b>

**INSPECTION**

Date of Assignment:	22/12/2022	
Date Inspected:	28/12/2022	Inspected At: Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Jan 2023)	
Parts:	N/A	HINO XZU710R 4.0 D 14FT WID CAB 5T (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP327C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,862.00 FL	*1,862.00 FL
2	1		*REAR TAIL LAMP	N/S Cracked	570.00 FL	*192.00 FL
3	1		*REAR TAIL LAMP BRACKET	Not Necessary	268.00 FL	*- FL
4	1		*REAR TAILGATE ALUMINIUM PLATE	Repair	900.00 FS	*- FS
5	2		*REAR MUDGUARDS	Cut / Distorted	3,200.00 FS	*500.00 FS
6	1		*REAR LOWER MEMBER (WOOD)	Cracked	900.00 FS	*900.00 FS
7	1		*REAR SAFETY BAR	Not Necessary	1,200.00 FS	*- FS
8	2		*REAR SAFETY BRACKET	Not Necessary	900.00 FS	*- FS
9	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
10	1		*REAR NUMBER PLATE BRACKET	Not Necessary	350.00 FS	*- FS
11	4		*REAR SAFETY BAR REFLECTORS	Not Necessary	140.00 FS	*- FS
12	1		*REAR STICKER (60KM)	Necessary	15.00 FS	*10.00 FS
13	1		*REAR STICKER (24 PAX)	Necessary	15.00 FS	*10.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					10,370.00	3,474.00
- List Item Discount on L Items 10.00/25.00% (S\$)					270.00	513.50
Total Parts (S\$)					10,100.00	2,960.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	120.00	20.00
2	TO REMOVE AND REPLACE SPARE PART ,PANEL BEATING AND CHASSIS REPAIR	New	2,100.00	800.00
3	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	900.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>3,120.00</b>	<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >