

Vehicle Damage Assessment Report for [YP327C]

Estimate Created: 17/01/2023 23:34 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 17/01/2023 23:38 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Hilux
Engine Type	1KDFTV		
License Plate Number	YP327C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum: \$3300.00 with 3 days for repair

Insurlogic 5 (17/01/2023 23:38)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR TAILGATE		1	1862.00	-25.00 %	1,396.50
REAR TAILLAMP		1	192.00	-25.00 %	144.00

Parts Subtotal 1,540.50

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR MUDGUARDS		1.0	500.00	0.00 %	500.00
REAR LOWER MEMBER WOOD		1.0	900.00	0.00 %	900.00
60KM STICKER		1.0	10.00	0.00 %	10.00
24 PAX STICKER		1.0	10.00	0.00 %	10.00

Materials Subtotal 1,420.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	20.00	0.00 %	20.00
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	800.00	0.00 %	800.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	400.00	0.00 %	400.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	820.00
		Paint Labor Subtotal	400.00
		Labor Subtotal	1,220.00

Summary

Repair Cost	4,180.50
Discount(21 %)	(880.50)
	3,300.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,300.00