

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22012800/TPA3Q2**Date:** 14/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900090612
Claimant Vehicle No :	SNC448K	Insured Vehicle No :	SMK8107L
Date of Loss:	18/12/2022	Nature of Claim:	TP
		Claim No:	8713746275SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC448K		
Make & Model:	MINI COOPER, 1.6 ABS D/AIRBAG 2WD 3DR (A)	Engine No:	A749I232
Reg. Date:	21/11/2008 (Man. Year: 2008)	Chassis No:	WMWMF72080TV04233
Colour:	Green	Odometer:	199450 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	'GREENTRAC' 6 mm	Rear Left Side:	'GREENTRAC' 6 mm
Front Right Side:	'GREENTRAC' 6 mm	Rear Right Side:	'GREENTRAC' 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,773.88	7,056.76	11,717.12	62.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.00	2,260.00	4,080.00	64.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,113.88	9,316.76	15,797.12	62.90
Approved Total (Overridden) (\$\$)		7,000.00		
Nett Amount (\$\$)	25,113.88	7,000.00	18,113.88	72.13
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	21/12/2022	
Date Inspected:	22/12/2022	Inspected At: TSL Auto Garage - AUTOBAY (HQ) 1 Kaki Bukit Avenue 6, Blk A Autobay #01-08 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Deformed	1,251.80 FL	*785.00 FL
2	1		*REAR BUMPER (LOWER)	Deformed	874.40 FL	*567.90 FL
3	1		*REAR BUMPER LOWER CENTRE COVER	Deformed	659.50 FL	*489.00 FL
4	2		*REAR BUMPER RETAINER	Not Necessary	184.20 FL	*- FL
5	2		*REAR BUMPER BRACKET	Not Necessary	126.80 FL	*- FL
6	1		*REAR BUMPER TOW COVER	Deformed	68.60 FL	*68.60 FL
7	1		*REAR LEFT BUMPER INNER SIDE TRIM	Not Necessary	91.60 FL	*- FL
8	1		*REAR RIGHT BUMPER INNER SIDE TRIM	Not Necessary	91.60 FL	*- FL
9	1		*REAR LEFT BUMPER SIDE PROTECTOR	Not Necessary	170.60 FL	*- FL
10	1		*REAR RIGHT BUMPER SIDE PROTECTOR	Not Necessary	170.60 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	520.80 FL	*485.00 FL
12	1		*REAR BUMPER CENTER SPONGE	Not Necessary	178.50 FL	*- FL
13	1		*SET REAR BUMPER REFLECTOR	Cracked	225.80 FL	*170.30 FL
14	1		*REAR TAILGATE ASSY	Bent	1,617.40 FL	*1,617.40 FL
15	1		*REAR TAILGATE CENTRE LOGO	Necessary	158.80 FL	*60.00 FL
16	1		*REAR TAILGATE S EMBLEM	Necessary	121.10 FL	*52.00 FL
17	1		*REAR TAILGATE COOPER EMBLEM	Necessary	160.10 FL	*58.00 FL
18	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	277.80 FL	*- FL
19	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	128.80 FL	*- FL
20	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	379.30 FL	*- FL
21	1		*REAR TAILGATE LOCK	Bent	182.50 FL	*182.50 FL
22	1		*REAR TAILGATE LOCK CATCH	Not Necessary	68.20 FL	*- FL
23	2		*REAR TAILGATE HINGES	Not Necessary	185.80 FL	*- FL
24	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	195.40 FL	*- FL
25	1		*SET REAR TAILGATE RUBBER STOPPER	Not Necessary	68.80 FL	*- FL
26	2		*REAR TAILGATE DAMPERS	Not Necessary	485.80 FL	*- FL
27	1		*REAR LEFT TAILLAMP	Not Necessary	899.70 FL	*- FL
28	1		*REAR RIGHT TAILLAMP	Not Necessary	899.70 FL	*- FL
29	1		*REAR LEFT TAILLAMP PROTECTOR	Not Necessary	156.60 FL	*- FL
30	1		*REAR RIGHT TAILLAMP PROTECTOR	Not Necessary	156.60 FL	*- FL
31	1		*REAR LEFT TAILLAMP OUTER GARNISH	Not Necessary	123.10 FL	*- FL
32	1		*REAR RIGHT TAILLAMP OUTER GARNISH	Not Necessary	123.10 FL	*- FL
33	1		*REAR LEFT FENDER PROTECTOR	Torn	187.50 FL	*187.50 FL
34	1		*REAR RIGHT FENDER PROTECTOR	Not Necessary	187.50 FL	*- FL
35	1		*REAR LEFT FENDER INNER SHIELD	Not Necessary	169.90 FL	*- FL
36	1		*REAR RIGHT FENDER INNER SHIELD	Not Necessary	169.90 FL	*- FL
37	1		*REAR LEFT FENDER INNER GARNISH	Not Necessary	396.30 FL	*- FL
38	1		*REAR RIGHT FENDER INNER GARNISH	Not Necessary	396.30 FL	*- FL
39	1		*REAR WIPER BLADE ASSY	Not Necessary	160.80 FL	*- FL
40	1		*REAR WIPER MOTOR	Not Necessary	353.60 FL	*- FL
41	2		*REAR AIR DUCT VENTILATOR	Not Necessary	160.20 FL	*- FL
42	1		*REAR END LOWER PANEL	Repair	1,256.30 FL	*- FL
43	1		*REAR END LOWER PANEL TOP GARNISH	Deformed	288.90 FL	*288.90 FL
44	1		*REAR EXHAUST MUFFLER ASSY	Bent	1,800.20 FL	*1,450.00 FL
45	2		*REAR EXHAUST MUFFLER RUBBER MOUNTINGS	Deformed	88.80 FL	*88.80 FL
46	1		*REAR EXHAUST MUFFLER HEAT SHIELD	Bent	179.90 FL	*179.90 FL
47	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	288.80 FL	*150.00 FL
48	10		*REAR BUMPER CLIPS (UPPER)	Necessary	60.00 FS	*30.00 FS
49	10		*REAR BUMPER CLIPS (LOWER)	Not Necessary	60.00 FS	*- FS
50	8		*REAR BUMPER LOWER CENTRE COVER CLIPS	Not Necessary	40.00 FS	*- FS
51	4		*REAR LEFT BUMPER SIDE PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
52	4		*REAR RIGHT BUMPER SIDE PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
53	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
54	4		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
55	1		*REAR LEFT FENDER PROTECTOR CLIPS	Necessary	30.00 FS	*20.00 FS

(6 PCS)

Report was unsubmitted during this print-out.

7/14/23, 1:17 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	6		*REAR RIGHT FENDER PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
57	6		*REAR LEFT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
58	6		*REAR RIGHT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
59	8		*REAR LEFT FENDER INNER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
60	8		*REAR RIGHT FENDER INNER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
61	1		*REAR END LOWER PANEL SEALANT	Not Necessary	140.00 FS	*- FS
62	1		*REAR END LOWER PANEL TOP GARNISH CLIPS (6 PCS)	Necessary	40.00 FS	*20.00 FS
63	4		*REAR BUMPER REVERSE SENSOR	Not Working (2 PCS ONLY)	1,200.00 FS	*400.00 FS
64	1		*REAR VIEW CAMERA	Not Necessary	450.00 FS	*- FS
65	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
66	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						19,628.30 7,400.80
- List Item Discount on L Items 5.00/5.00% (\$\$)						854.42 344.04
Total Parts (\$\$)						18,773.88 7,056.76
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	700.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	80.00
6	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	150.00	60.00
7	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	30.00
8	TO INSTALL COLOUR WRAPPING STICKER TO REAR PORTION	New	3,000.00	500.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	40.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
11	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	40.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (S\$)			6,340.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >