

ASS. REC. BY: Taj

REF:

ASSIGNMENT

2028 Nov

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$64K.

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC448K Yr Regn: 2008, M

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mini Cooper S c.c. 1598

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 199450 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM WM F7 20807604253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R17

R: M

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green MC

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 22/12/22 @ 12pm

Survey held at TSL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Photos _____

Others _____

Rep. Format: _____
Lump Sum / L.B.B. / _____

TOTAL

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SNC448K Mini Cooper S

No	Qty	Parts Description	Estimated Parts Price	
41	2	Rear air duct ventilator	\$ 160.20	X ny
42	1	Rear end lower panel	\$ 1,256.30	Rx
43	1	Rear end lower panel top garnish	\$ 288.90	de✓
44	1	Rear exhaust muffler assy	\$ 1,800.20	bt✓ 1450
45	2	Rear exhaust muffler rubber mountings	\$ 88.80	de✓
46	1	Rear exhaust muffler heat shield	\$ 179.90	bt✓
47	1	Rear windscreen glass moulding	\$ 288.80	new✓ 150
			\$ 4,063.10	
		less 5%	\$ 203.16	6880.80
			\$ 3,859.95	6536.76

Special Nett Items

1	10	Rear bumper clips (upper)	\$ 60.00	30 new✓
2	10	Rear bumper clips (lower)	\$ 60.00	X
3	8	Rear bumper lower centre cover clips	\$ 40.00	X
4	4	Rear left bumper side protector clips	\$ 30.00	X
5	4	Rear right bumper side protector clips	\$ 30.00	X
6	8	Rear tailgate inner trim board clips	\$ 40.00	X
7	4	Rear tailgate outer garnish clips	\$ 30.00	X
8	6	Rear left fender protector clips	\$ 30.00	20 new✓
9	6	Rear right fender protector clips	\$ 30.00	X ny
10	6	Rear left fender inner shield clips	\$ 40.00	X
11	6	Rear right fender inner shield clips	\$ 40.00	X
12	8	Rear left fender inner garnish clips	\$ 40.00	X
13	8	Rear right fender inner garnish clips	\$ 40.00	X
14	1	Rear end lower panel sealant	\$ 140.00	X
15	6	Rear end lower panel top garnish clips	\$ 40.00	20 new✓
16	2	Rear bumper reverse sensor	\$ 1,200.00	new✓ 400
17	1	Rear view camera	\$ 450.00	X
18	1	Rear no plate with garnish	\$ 100.00	X
19	1	Rear windscreen glass sealant	\$ 100.00	50 new✓
			\$ 2,540.00	520

Total parts

\$ 18,773.89

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SNC448K Mini Cooper S

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00 600
2	To putty and spray painting rear portion.	\$ 1,200.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 60
5	To remove and install rear exhaust muffler assy.	\$ 120.00 80
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 60
7	To apply anti rust proofing to rear affected area.	\$ 140.00 30
8	To install colour wrapping sticker to rear portion	\$ 3,000.00 500
9	To remove and install rear bumper reverse sensor.	\$ 80.00 40
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120
11	To remove and install rear view camera.	\$ 80.00 40
12	Towing service.	\$ 100.00 Xnn
Total labour :		\$ 6,340.00 2260

Total parts : \$ 18,773.89

Total labour : \$ 6,340.00

Total repair cost : \$ 25,113.89

6536.76
 820
 2260
 9316.76
 4157450
 06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: