

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22012803/AQY3E2
Date: 04/05/2023**REFERENCE**Insured/Claimant: WANG HUIMIN BETHANY Policy No: 7220086642
Date of Loss: 16/12/2022 Nature of Claim: OD Claim No: 1835962036SG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNG3856A**
Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM032134
Reg. Date: 29/07/2022 (Man. Year: 2021) Chassis No: WAUZZZF47MA065811
Colour: Black Odometer: 5039 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$240,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,735.00	7,842.40	16,892.60	68.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,542.00	6,342.00	2,200.00	25.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,277.00	14,184.40	19,092.60	57.37
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	32,177.00	13,084.40	19,092.60	59.34
+ GST 8.00/8.00% (S\$)	2,574.16	1,046.75	1,527.41	59.34
Nett Amount (S\$)	34,751.16	14,131.15	20,620.01	59.34

INSPECTIONDate of Assignment: 23/12/2022
Date Inspected: 21/12/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 8.0 days**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	293.00 FS	*234.00 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Missing	51.00 FS	*40.08 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	293.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER OUTER GRILLE HOLE COVER - LH	Missing	54.00 FS	*42.64 FS
10	1		*RADIATOR GRILLE	Cracked	1,754.00 FS	*1,403.20 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	212.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
13	1		*FRONT BUMPER BRACKET - LH	Not Necessary	254.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
17	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
18	1		*FRONT BUMPER BRACKET	Not Necessary	154.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
20	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
21	1		*HORN BRACKET - LH	Not Necessary	33.00 FS	*- FS
22	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	532.00 FS	*- FS
23	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
24	1		*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
25	1		*HEADLIGHT - LH	Not Necessary	8,172.00 FS	*- FS
26	1		*LIFT CYLINDER - LH	Not Necessary	231.00 FS	*- FS
27	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
28	1		*LOCK CARRIER	Cracked	1,478.00 FS	*1,255.20 FS
29	1		*LOCK CARRIER SUPPORT	Not Necessary	43.00 FS	-
30	1		*CHARGE AIR COOLER	Dented	654.00 FS	*522.80 FS
31	1		*CHARGE AIR COOLER PRESSURE PIPE - LH	Not Necessary	496.00 FS	*- FS
32	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
33	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	186.00 FS	*- FS
34	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	381.00 FS	*- FS
35	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	277.00 FS	*- FS
36	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
37	1		*RADIATOR	Dented	699.00 FS	*574.40 FS
38	6		*READY-MIX COOLANT	Necessary	297.00 FS	*260.16 FS
39	1		*RADIATOR AIR GUIDE - LH INNER	Damaged	51.00 FS	*29.84 FS
40	1		*RADIATOR AIR GUIDE - LH OUTER	Not Necessary	19.00 FS	*- FS
41	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	44.00 FS	*- FS
42	1		*FRONT NOISE INSULATION	Torn	640.00 FS	*546.00 FS
43	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	256.00 FS	*- FS
44	1		*FRONT WHEEL SPOILER - LH	Cracked	82.00 FS	*68.96 FS
45	1		*FRONT WHEEL SPOILER END PLATE - LH	Not Necessary	39.00 FS	*- FS
46	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
47	1		*SUNDRIES	Necessary	400.00 FS	*35.92 FS
48	1		*LIFT CYLINDER CORRUGATED PIPE	Damaged	107.00 FS	*88.80 FS
49	1		*FRONT WISHBONE LINK-LH (Supplementary)	Cut	605.00 FS	*483.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 24,735.00 7,842.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	2,000.00
6	TO RESPRAY FRONT BUMPER	New	900.00	550.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO DISMANTLE AND RENEW LH FRONT WISHBONE LINK. (Supplementary)	New	280.00	280.00
9	TO CARRY OUT WHEEL ALIGNMENT (Supplementary)	New	240.00	240.00
Gross Labour Cost (S\$)			8,542.00	6,342.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >