

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22012807/AVCM4**Date:** 27/03/2023**REFERENCE**

Insured/Claimant: CAROLYN JOYCE TIEMANN Policy No: 7210046972
Date of Loss: 16/12/2022 Nature of Claim: OD Claim No: 9592623723SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ7820M**
Make & Model: AUDI Q3, 1.4 TFSI S TRONIC (17") (A) Engine No: CZDC39824
Reg. Date: 18/05/2021 (Man. Year: 2021) Chassis No: WAUZZZF31M1117022
Colour: Black Odometer: 15970 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$165,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,232.00	1,787.60	9,444.40	84.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	2,272.00	3,700.00	61.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,204.00	4,059.60	13,144.40	76.40
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	16,804.00	3,659.60	13,144.40	78.22
+ GST 8.00/8.00% (S\$)	1,344.32	292.77	1,051.55	78.22
Nett Amount (S\$)	18,148.32	3,952.37	14,195.95	78.22

INSPECTION

Date of Assignment: 23/12/2022
Date Inspected: 21/12/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,073.00 FS	*858.40 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	66.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	171.00 FS	*136.40 FS
4	1		*FRONT BUMPER GRILLE - LH	Not Necessary	124.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Cut	426.00 FS	*340.80 FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	43.00 FS	*- FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	137.00 FS	*- FS
9	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
10	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
11	1		*FRONT FENDER - LH	Repair	1,445.00 FS	*- FS
12	1		*FRONT FENDER BRACE - LH	Not Necessary	98.00 FS	*- FS
13	1		*FRONT FENDER BRACKET - LH	Not Necessary	39.00 FS	*- FS
14	1		*HEADLIGHT MOUNTING - LH	Not Necessary	132.00 FS	*- FS
15	1		*HEADLIGHT - LH	Not Necessary	5,952.00 FS	*- FS
16	1		*LIFT CYLINDER - LH	Not Necessary	231.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
18	2		*FRONT WHEEL COVER - LH / RH	N/s Cut / O/s Necessary	566.00 FS	*452.00 FS
19	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,232.00 1,787.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,972.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >