

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012811/AVY3Q2**Date:** 20/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00143372203

Claimant Vehicle No : SKU8048U **Insured Vehicle No :** SJR6403T

Date of Loss: 19/12/2022 Nature of Claim: TP Claim No: SNM22D209157/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU8048U**

Make & Model: PORSCHE CAYENNE, 3.0 (A) Engine No: DCB185556

Reg. Date: 20/08/2020 (Man. Year: 2019) Chassis No: WP1ZZZ9YZLDA02517

Colour: Black Odometer: 29146 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 315/35 R21 Rear Tyre Size: 315/35 R21

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,358.10	2,110.00	16,248.10	88.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,940.00	1,240.00	5,700.00	82.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,298.10	3,350.00	21,948.10	86.76
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	25,298.10	2,650.00	22,648.10	89.52
+ GST 8.00/8.00% (S\$)	2,023.85	212.00	1,811.85	89.52
Nett Amount (S\$)	27,321.95	2,862.00	24,459.95	89.52

INSPECTION

Date of Assignment: 22/12/2022

Date Inspected: 23/12/2022 Inspected At: Xin Yun Auto Private Limited (HQ)
1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	M1-SUV	PORSCHE CAYENNE 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU8048U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	3,857.15 F	*- FL
2	1		*BUMPER SIDE BRACKET	Cracked	600.00 F	*300.00 FL
3	1		*REAR REINFORCEMENT	Not Necessary	3,190.00 F	*- FL
4	1		*TOW COVER	Not Necessary	150.00 F	*- FL
5	1		*LOWER LIP UPPER MATT BLACK	Cut	2,865.15 F	*1,220.00 FL
6	1		*LOWER LIP LOWER MATT BLACK	Not Necessary	2,690.00 F	*- FL
7	1		*PORSCHE LOGO	Not Necessary	380.00 F	*- FL
8	1		*CAYENNE LOGO	Not Necessary	220.00 F	*- FL
9	1		*REAR RUBER STRIP	Not Necessary	495.80 F	*- FL
10	2		*REAR BUMPER SENSOR LEFT SIDE	Not Necessary	900.00 F	*- FL
11	2		*EXHAUST HEAT SHIELD	Not Necessary	800.00 F	*- FL
12	1		*EXHAUST COVER LEFT	Not Necessary	500.00 F	*- FL
13	1		*BUMPER CABEL HOLDER -SINGLE USE ONE SET	Necessary	180.00 F	*180.00 FL
14	2		*WHEEL HOUSING TRIM LINNING 2 JOINT PIECE	Necessary	950.00 F	*500.00 FL
15	10		*REAR BUMPER CLIPS	Necessary	120.00 FS	*50.00 FS
16	12		*REAR BUMPER SIDE COVER CLIPS	Not Necessary	80.00 FS	*- FS
17	1		*REAR LOWER LIP UPPER GARNISH CLIPS	Necessary	100.00 FS	*50.00 FS
		(6 PCS)				
18	8		*REAR LOWER LIP LOWER GARNISH CLIPS	Not Necessary	120.00 FS	*- FS
19	12		*WHEEL HOUSING TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
20	1		*REAR NO PLATE WITH CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,358.10	2,330.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	220.00
Total Parts (\$\$)	18,358.10	2,110.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS ,INCLUDING REAR END PANEL	New	2,500.00	350.00
2	TO PUTTY AND SPRAY PAINTING DAMAGED AREA	New	2,500.00	350.00
3	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	250.00	0.00
4	TO CHECK REAR LIGHTING AND WIRING	New	120.00	30.00
5	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	150.00	60.00
6	TO CONDUCT WHEEL ALIGNMENT -REAR LEFT	New	150.00	0.00
7	CEREMIC COATING FOR REAR	New	600.00	300.00
8	WATER TEST AFTER REPAIR	New	120.00	0.00
9	REMOVE BOTH FENDER INTERNAL TRIM TO FACILITATE THIS REPAIR	New	250.00	0.00
10	RE-PROGRAMMING AND RE-SET SYSTEM ,REMOVE ACCIDENT FAULT CODE	New	300.00	150.00
Gross Labour Cost (S\$)			6,940.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >