

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI22012812/TVY3Q2**Date:** 20/04/2023**REFERENCE**Insured/Claimant: - Policy No: DMPCSNW00120022201  
Date of Loss: 17/12/2022 Nature of Claim: OD Claim No: SNM22D209113/C01/TANCHC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMW4590L**  
Make & Model: BMW 216I, 1.5 GRAN TOURER (A) Engine No: 42725740B38A15A  
Reg. Date: 21/11/2019 (Man. Year: 2019) Chassis No: WBA6V120705N97663  
Colour: Silver Odometer: 29534 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: S\$115,000.00  
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,079.10	4,683.65	395.45	7.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,465.00	6,123.00	4,342.00	41.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,544.10</b>	<b>10,806.65</b>	<b>4,737.45</b>	<b>30.48</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	15,044.10	10,306.65	4,737.45	31.49
<b>+ GST 8.00/8.00% (S\$)</b>	1,203.53	824.53	379.00	31.49
<b>Nett Amount (S\$)</b>	<b>16,247.63</b>	<b>11,131.18</b>	<b>5,116.45</b>	<b>31.49</b>

**INSPECTION**

Date of Assignment: 22/12/2022

Date Inspected: 23/12/2022 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance  
Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
<b>Parts:</b> M1-MPV	BMW 216I 1.5 GRAN TOURER (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMW4590L)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS	
2	1		*FRT LH FENDER	Bent	639.70 FS	*639.70 FS	
3	1		*LH EXTENSION WHEEL HOUSING STRUT	Bent	173.00 FS	*173.00 FS	
4	1		*LH CROSS SUPPORT SIDE PANEL	Not Necessary	33.10 FS	*- FS	
5	1		*LH FOG LAMP SUPPORT	Not Necessary	80.55 FS	*- FS	
6	1		*LH MOULDING (LUXURY)	Not Necessary	69.15 FS	*- FS	
7	1		*LH FINISHER	Cut	53.30 FS	*53.30 FS	
8	1		*FRT BUMPER PRIMED PANEL (PMA)	Deformed	950.80 FS	*950.80 FS	
9	1		*LH GRID LATERAL (LINES/PDC)	Cut	96.95 FS	*96.95 FS	
10	2		*GROMMET	Not Necessary	1.60 FS	*- FS	
11	1		*LH SUPPORT HEADLIGHT ARM	Deformed	78.50 FS	*78.50 FS	
12	1		*FRT LH WHEEL ARCH COVER	Not Necessary	138.40 FS	*- FS	
13	1		*LH AIR DUCT DISPLACED RADIATOR	Not Necessary	72.65 FS	*- FS	
14	1		*PLAQUE 82MM	Necessary	72.85 FS	*72.85 FS	
15	1		*FRT BUMPER LH INSERT	Deformed	14.20 FS	*14.20 FS	
16	1		*FRT LH SIDE PANEL TOP MOUNTING	Deformed	18.90 FS	*18.90 FS	
17	4		*EXPANDING RIVET	Necessary	1.80 FS	*1.80 FS	
18	1		*FRT LH FENDER SEALING	Necessary	34.55 FS	*34.55 FS	
19	1		*LH HEADLIGHT LED TECHNOLOGY	Cracked	2,399.10 FS	*2,399.10 FS	
					<b>Total Parts (\$)</b>	<b>5,079.10</b>	<b>4,683.65</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER ,SUPPORT LEFT ,REINFORCEMENT ATTACHMENTS AND MAKE GOOD OF BONNET AND FRONT LEFT DOOR	New	5,100.00	2,550.00
2	TO PAINTING FRONT BUMPER ,FENDER LEFT ,BONNET AND FRONT LEFT DOOR	New	4,412.00	2,668.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO REPLACE LEFT OR RIGHT HEADLIGHT	New	481.00	457.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
			<b>Gross Labour Cost (S\$)</b>	<b>10,465.00</b>
				<b>6,123.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >