

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012814/RVY3Q2**Date:** 03/04/2023**REFERENCE**

| | | | |
|------------------------------|---|-----------------------------|--------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSNW00218332204 |
| Claimant Vehicle No : | SLQ9799M | Insured Vehicle No : | SLX9255D |
| Date of Loss: | 19/12/2022 | Nature of Claim: | TP |
| | | Claim No: | SNM22D209122/C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLQ9799M | Engine No: | 33006357B38A15A |
| Make & Model: | BMW 216I, 1.5 (A) | Chassis No: | WBA6V120805T50443 |
| Reg. Date: | 24/06/2021 (Man. Year: 2021) | Odometer: | 29696 km |
| Colour: | Black | | |
| Engine Capacity: | 1499 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55 R17 | Rear Tyre Size: | 205/55 R17 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 1,793.60 | 1,244.10 | 549.50 | 30.64 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,520.00 | 3,862.00 | 658.00 | 14.56 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 6,313.60 | 5,106.10 | 1,207.50 | 19.13 |
| + GST 8.00/8.00% (S\$) | 505.09 | 408.49 | 96.60 | 19.13 |
| Nett Amount (S\$) | 6,818.69 | 5,514.59 | 1,304.10 | 19.13 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 22/12/2022 | Performance Motors Limited (Alexandra) |
| Date Inspected: | 11/01/2023 Inspected At: | 303 Alexandra Road, Sime Darby Performance Centre |
| Estimated Period of Repair: | 4.0 days | Singapore 159941 |

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 03 Apr 2023) |
| Parts: | M1-MPV | BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLQ9799M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|---------------------------------------|---------------|-------------------|-------------------|
| 1 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *80.00 FS |
| 2 | 2 | | *C CLIP FOR PLASTIC NUT | Not Necessary | 2.20 FS | *- FS |
| 3 | 2 | | *C-CLIP | Not Necessary | 3.40 FS | *- FS |
| 4 | 1 | | *REAR BUMPER CARRIER | Not Necessary | 490.70 FS | *- FS |
| 5 | 1 | | *SUPPORT | Not Necessary | 47.00 FS | *- FS |
| 6 | 2 | | *PLUG IN NUT | Not Necessary | 6.20 FS | *- FS |
| 7 | 1 | | *REAR BUMPER TRIM STRIP (BLACK) | Scratched | 75.80 FS | *75.80 FS |
| 8 | 1 | | *REAR BUMPER PANEL PRIMED (LINES PDC) | Deformed | 1,088.30 FS | *1,088.30 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| | | | | | Total Parts (S\$) | 1,793.60 1,244.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER AND MAKE GOOD TAILGATE | New | 2,125.00 | 1,700.00 |
| 2 | TO RESPRAY REAR BUMPER AND TAILGATE | New | 1,923.00 | 1,826.00 |
| 3 | TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| 4 | TO CHECK ELECTRICAL | New | 177.00 | 168.00 |
| 5 | TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) | New | 118.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 4,520.00 | 3,862.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >