

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012815/RVY3M4**Date:** 22/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00265062201		
Claimant Vehicle No :	SKE1088J	Insured Vehicle No :	SML5983M		
Date of Loss:	21/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209177/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1088J	Engine No:	DLB030833
Make & Model:	SKODA OCTAVIA, 2.0 RS TSI (A)	Chassis No:	TMBBU7NE2K0161365
Reg. Date:	27/08/2019 (Man. Year: 2019)	Odometer:	60279 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 ZR18	Rear Tyre Size:	225/40 ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,724.14	6,733.51	6,990.63	50.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,690.00	11,470.00	6,220.00	35.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,414.14	18,203.51	13,210.63	42.05
+ GST 8.00/8.00% (S\$)	2,513.13	1,456.28	1,056.85	42.05
Nett Amount (S\$)	33,927.27	19,659.79	14,267.48	42.05

INSPECTION

Date of Assignment:	22/12/2022	
Date Inspected:	27/12/2022	Inspected At: VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934
Estimated Period of Repair:	14.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	143	SKODA OCTAVIA 2.0 RS TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE1088J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER RHS FRT FENDER	Repair	767.75 FS	*- FS
2	4		*RIVETTED CAP NUT	Not Necessary	10.56 FS	*- FS
3	1		*WHEELHOUSE RHS FENDER LINER	Not Necessary	194.61 FS	*- FS
4	1		*UNBEKANNT RHS FRT DOOR	Bent	2,879.34 FS	*2,879.34 FS
5	1		*DOOR SEAL	Necessary	85.59 FS	*85.59 FS
6	1		*ALU-LAMIN.INSULATION DOOR INSULATOR	Necessary	43.65 FS	*43.65 FS
7	4		*UNBEKANNT RIVET NUT	Necessary	2.12 FS	*2.12 FS
8	2		*HEXAGON SOCKET FLAT HEAD	Necessary	3.96 FS	*3.96 FS
9	1		*MOLDING FO RHS FRT SCUFF PLATE	Not Necessary	245.67 FS	*- FS
10	1		*SECTIONAL ROCKER PANEL RH	Bent	1,134.51 FS	*1,134.51 FS
11	1		*2K-INSERT FOAM	Necessary	163.23 FS	*163.23 FS
12	1		*SEALANT CAN BE SPRAYED	Necessary	66.78 FS	*66.78 FS
13	1		*ZINC SPRAY	Necessary	72.86 FS	*72.86 FS
14	1		*2K-BODY ADHESIVE	Necessary	469.52 FS	*469.52 FS
15	1		*LONG-LIFE UNDERSEAL	Necessary	92.69 FS	*92.69 FS
16	1		*UNBEKANNT STICKER (CHASSIS NO)	Necessary	239.78 FS	*239.78 FS
17	1		*FOIL RHR FENDER FOIL	Necessary	44.93 FS	*44.93 FS
18	1		*UNBEKANNT RHS REAR DOOR	Repair	2,879.34 FS	*- FS
19	1		*ALU-LAMIN.INSULATION DOOR INSULATOR	Not Necessary	43.65 FS	*- FS
20	1		*DOOR SEAL	Not Necessary	103.06 FS	*- FS
21	1		*DOOR SEAL RHR DOOR SEAL (SIDE)	Not Necessary	72.78 FS	*- FS
22	4		*UNBEKANNT RIVET NUT	Not Necessary	2.12 FS	*- FS
23	2		*HEXAGON SOCKET FLAT HEAD	Not Necessary	3.96 FS	*- FS
24	1		*ALLOY WHEEL	Not Necessary	1,465.00 FS	*- FS
25	1		*RUBBER VALVE	Not Necessary	3.85 FS	*- FS
26	1		*TIE ROD	Not Necessary	139.18 FS	*- FS
27	1		*BOLT HEX. HD. WITH SHOULD	Not Necessary	10.10 FS	*- FS
28	1		*SHOULDERED HEX. NUT SELF-	Not Necessary	3.60 FS	*- FS
29	1		*BOLT HEX. HD. WITH SHOULD	Not Necessary	11.07 FS	*- FS
30	2		*SHOULDERED HEX. NUT SELF-	Not Necessary	6.76 FS	*- FS
31	2		*HEXAGON FLANGE SCREW	Not Necessary	11.24 FS	*- FS
32	2		*SHOULDERED HEX. NUT SELF-	Not Necessary	6.76 FS	*- FS
33	1		*TRAILING ARM	Not Necessary	340.42 FS	*- FS
34	1		*SCREW HEX. HD.	Not Necessary	11.33 FS	*- FS
35	2		*FITTED BOLT HEX. HEAD	Necessary	18.10 FS	*18.10 FS
36	4		*BOLT HEX. HD.	Not Necessary	24.08 FS	*- FS
37	1		*UNBEKANNT WHEEL BEARING	Bent	509.74 FS	*509.74 FS
38	1		*BOLT	Necessary	11.33 FS	*11.33 FS
39	1		*CAP	Necessary	9.46 FS	*9.46 FS
40	1		*WHEEL BEARING HOUSING	Bent	762.91 FS	*762.91 FS
41	1		*BONDED RUBBER MOUNTING	Cut	31.73 FS	*31.73 FS
42	1		*BOLTHEX.HD.WITH SHOUL.	Necessary	9.53 FS	*9.53 FS
43	1		*SHOULDERED HEX. NUT SELF-	Necessary	3.60 FS	*3.60 FS
44	1		*BOLT HEX. HD.	Necessary	9.62 FS	*9.62 FS
45	1		*SHOULDERED HEX. NUT	Necessary	6.02 FS	*6.02 FS
46	1		*TRACK CONTROL ARM	Not Necessary	325.56 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*RHR UPPER ARM ECCENTRIC SCREW	Bent	17.97 FS	*17.97 FS
48	1		*SHOULDERED HEX. NUT SELF-	Necessary	3.60 FS	*3.60 FS
49	1		*TRACK CONTROL ARM RHR LOWER ARM	Not Necessary	294.48 FS	*- FS
50	1		*ECCENTRIC SCREW	Necessary	18.54 FS	*18.54 FS
51	1		*SHOULDERED HEX. NUT SELF-	Necessary	3.60 FS	*3.60 FS
52	1		*BOLT HEX. HD. WITH SHOULD	Not Necessary	10.10 FS	*- FS
53	1		*SHOULDERED HEX. NUT SELF-	Not Necessary	3.60 FS	*- FS
54	1		*DEGREASER CLEANER 500ML	Necessary	18.80 FS	*18.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	13,724.14	6,733.51
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	B&P WHEEL ALIGNMENT	New	360.00	360.00
4	R&R RIM & BALANCE	New	50.00	50.00
5	R&R RHR U/CARRIAGE	New	2,520.00	0.00
6	LABOUR	New	6,720.00	5,880.00
7	SPRAY PAINT	New	5,600.00	4,000.00
8	TRANSFER DOOR MECHANISM	New	1,680.00	420.00
Gross Labour Cost (S\$)			17,690.00	11,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >