

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012816/KQY3M4**Date:** 05/05/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002077056

Claimant Vehicle No : SLT2346S**Insured Vehicle No :** SKQ5974L

Date of Loss: 21/12/2022

Nature of Claim: TP

Claim No: 295924

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT2346S**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4423504

Reg. Date: 23/10/2017 (Man. Year: 2017)

Chassis No: RU11223502

Colour: Metallic Red

Odometer: 121100 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Michelin 9 mm

Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,068.80	2,706.20	6,362.60	70.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,275.00	1,745.00	57.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,088.80	3,981.20	8,107.60	67.07
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	12,088.80	3,200.00	8,888.80	73.53

INSPECTION

Date of Assignment: 23/12/2022

Date Inspected: 28/12/2022

Inspected At:

A T AUTO CONSULTANT
113 TECK WHYE LANE,
#05-650, SINGAPORE 680113

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT2346S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,100.00 FL	*566.00 FL
2	2		*REAR CORNER PANEL LH/RH	Serviceable	596.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	118.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR LH/RH	Serviceable	302.00 FL	*- FL
5	1		*TAILGATE	Bent	1,386.00 FL	*953.00 FL
6	1		*TAILGATE REFLECTOR LH/RH	Serviceable	824.00 FL	*- FL
7	1		*TAILGATE LOCK	Dented	339.00 FL	*250.50 FL
8	1		*TAILGATE INNER TRIM	Mtg Cracked	301.00 FL	*250.50 FL
9	1		*TAILGATE WINDSCREEN SEAL	Necessary	385.00 FL	*112.20 FL
10	1		*TAILGATE WEATHERSTRIP (\$298.00) (50%) (SN)	Cut	256.80 FS	*149.00 FS
11	1		*TAILGATE EMBLEM VEZEL	Necessary	72.00 FL	*72.00 FL
12	1		*TAILGATE MOULDING	Serviceable	422.00 FL	*- FL
13	1		*TAILLAMP LH/RH	Serviceable	934.00 FL	*- FL
14	1		*TAILLAMP CORNER PANEL LH/RH	Serviceable	562.00 FL	*- FL
15	1		*REAR END PANEL	Bent	556.00 FL	*411.90 FL
16	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	286.00 FL	*180.90 FL
17	1		*REAR FLOOR PANEL	Repair	912.00 FL	*- FL
18	1		*REAR FLOOR PANEL TOP GARNISH	Serviceable	378.00 FL	*- FL
19	1		*REAR FLOOR PANEL UNDER COVER	Serviceable	365.00 FL	*- FL
20	1		*REAR TOOL BOX GARNISH	Serviceable	265.00 FL	*- FL
21	1		*REMOTE KEY BUZZER	Cracked	87.00 FL	*87.00 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
23	1		*SET REVERSE SENSOR	Dented/Shorted	330.00 FS	*200.00 FS
24	1		*SET REAR NUMBER PLATE & GARNISH	Serviceable	100.00 FS	*- FS
25	1		*REVERSE CAM	Serviceable	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,106.80	3,283.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,038.00	576.80
Total Parts (\$\$)	9,068.80	2,706.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,200.00	600.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,200.00	400.00
3	WIRING CHARGES	New	100.00	15.00
4	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	120.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	50.00	50.00
6	REMOVE/REFIX TAILGATE COMPONENTS	New	100.00	60.00
7	REMOVE/REFIX TAILGATE WINDSCREEN	New	250.00	120.00
Gross Labour Cost (S\$)			3,020.00	1,275.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >