

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI22012817/GQY3E2**Date:** 19/04/2023**REFERENCE**

Insured/Claimant: SOLLIHIN BIN SUKHAIRI Policy No: DMHCSNW00023232200

Date of Loss: 19/12/2022

Nature of Claim: OD

Claim No: SNM22D209158/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNH8716H**

Make &amp; Model: MERCEDES-BENZ CLA250 AMG A, 2.0 (A)

Engine No: 26092030293534

Reg. Date: 01/12/2022 (Man. Year: 2021)

Chassis No: W1K1183462N196376

Colour: Blue

Odometer: 1978 km

Engine Capacity: 1991 cc

Market Value/New Car Price: S\$253,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,555.00	5,015.00	2,540.00	33.62
Miscellaneous Items	85.00	85.00	0.00	0.00
Labour	365.40	340.20	25.20	6.90
Paintwork Labour	575.55	526.02	49.53	8.61
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,580.95</b>	<b>5,966.22</b>	<b>2,614.73</b>	<b>30.47</b>
<b>- Excess (S\$)</b>	0.00	2,500.00	-2,500.00	
<b>(S\$)</b>	8,580.95	3,466.22	5,114.73	59.61
<b>+ GST 7.00/8.00% (S\$)</b>	600.67	277.30	323.37	53.83
<b>Nett Amount (S\$)</b>	<b>9,181.62</b>	<b>3,743.52</b>	<b>5,438.10</b>	<b>59.23</b>

**INSPECTION**

Date of Assignment:	23/12/2022	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	23/12/2022	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands)
			6 Marsiling Lane
			Singapore 739145
Estimated Period of Repair:	6.0 days		

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
<b>Parts:</b>	143	MERCEDES-BENZ CLA250 AMG A 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNH8716H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		7,555.00 F	*5,015.00 F
						F=Franchise part.
<b>Total Parts (S\$)</b>					<b>7,555.00</b>	<b>5,015.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	85.00	85.00
Sub Total (\$)			85.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	575.55	526.02
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	365.40	340.20
Gross Labour Cost (\$)			940.95	866.22

Report was unsubmitted during this print-out.

< END OF ESTIMATES >