2/14/23, 1:54 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd. Our File No: CS/CTI22012818/GWY3M4 3 Anson Road, #16-00 Springleaf Tower

Date: 14/02/2023 Singapore 079909

REFERENCE

Insured/Claimant: JIN SHENG PTE LTD Policy No: DMCVSNW00066032200

Date of Loss: 08/12/2022 Nature of Claim: OD Claim No: SNM22D208861/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ754Y**

Make & Model: ISUZU NNR85UH4A, 3.0 D (M) 4JJ14A3367 Engine No:

27/05/2019 (Man. Year: 2019) JAANNR85HK7100175 Reg. Date: Chassis No:

Colour: White Odometer: 283522 km

Engine Capacity: 2999 cc

Market Value/New Car

S\$95,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/85 R16 Rear Tyre Size: 195 R15

Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		17,335.00	7,770.00	9,565.00	55.18
Miscellaneous Items		800.00	0.00	800.00	100.00
Labour		4,578.00	4,578.00	0.00	0.00
Paintwork Labour		1,182.12	1,182.12	0.00	0.00
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	23,895.12	13,530.12	10,365.00	43.38
	- Excess (S\$)	550.00	550.00	0.00	0.00
	(S\$)	23,345.12	12,980.12	10,365.00	44.40
	+ GST 7.00/7.00% (S\$)	1,634.16	908.61	725.55	44.40
	Nett Amount (S\$)	24,979.28	13,888.73	11,090.55	44.40

INSPECTION

Auto Insure Pte Ltd (HQ) (Woodlands) Date of Assignment: 23/12/2022 Present Location:

Auto Insure Pte Ltd (HQ) (Woodlands)

6 Marsiling Lane Date Inspected: 23/12/2022 Inspected At:

Singapore 739145

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$10,365.00 NETT)

TOTAL LOSS ASPECT

\$95,000.00 Market Value : OMV: \$33,520.00

PARF Rebate (1): \$0.00

Quota Premium Paid: \$26,722.00 COE Rebate (2): \$17,146.00 Total Rebate (1) + (2) = : \$17,146.00

The total amount incurred will be Market Value \$95,000.00 minus Total Rebate \$17,146.00 = \$77,854.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

2/14/23, 1:54 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Feb 2023)

Parts: N/A ISUZU NNR85UH4A 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YQ754Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*PARTS		17,335.00 F	*7,770.00 F
i –i ianonise part.		Total Parts (S\$)	17,335.00	7,770.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 EXTRAS		800.00	0.00
	Sub Total (S\$)	800.00	0.00
Recommended Labour			
No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 LABOUR FOR SPRAY PAINTING	New	1,182.12	1,182.12
<u>Labour Items</u>			
2 LABOUR FOR PANEL BEATING	New	4,578.00	4,578.00
	Gross Labour Cost (S\$)	5,760.12	5,760.12
Report wa	s unsubmitted during this print-out.		

< END OF ESTIMATES >