

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 8525E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEEP CUT	1,280.00	845.20
1	REAR BUMPER TOW COVER	NOT NECESSARY	20.00	-
2	REAR BUMPER SIDE RETAINERS @\$151.00	O/S CRACKED (1PC ONLY)	302.00	86.50
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR AIR VENT O/S	NOT NECESSARY	115.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	665.20	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	341.10	-
1	TAILLAMP O/S	SCRATCHED	850.00	402.10
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,190.00	-
	LESS 25% DISCOUNT		-	-345.95
			4,813.30	1,037.85
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
			730.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	60.00
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.	NOT NECESSARY	180.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER AND REAR FENDER O/S.		800.00	320.00
	TO PUTTY & SPRAY PAINTING.		800.00	400.00
			2,130.00	850.00
	GRAND TOTAL		7,673.30	1,887.85

Report Ref No. CS/FCI22012820/Uny3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,500.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI22012820/Uny3m4

MARKET VALUE: \$35,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,733.00=NETT VALUE: \$19,267.00

CHUA KANG SENG

Licensed Appraiser