

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012821/RQY3Q2**Date:** 07/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00005152201		
Claimant Vehicle No :	SNA4712G	Insured Vehicle No :	SMZ370R		
Date of Loss:	21/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209208/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA4712G	Engine No:	40406383B38A15A
Make & Model:	BMW 216I, 1.5 GRAN TOURER (A)	Chassis No:	WBA6V120505T62176
Reg. Date:	24/06/2021 (Man. Year: 2021)	Odometer:	31373 km
Colour:	Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,698.85	3,510.70	3,188.15	47.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,983.00	5,384.00	1,599.00	22.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,681.85	8,894.70	4,787.15	34.99
+ GST 8.00/8.00% (S\$)	1,094.55	711.58	382.97	34.99
Nett Amount (S\$)	14,776.40	9,606.28	5,170.12	34.99

INSPECTION

Date of Assignment:	23/12/2022	Performance Motors Limited (Alexandra)
Date Inspected:	09/01/2023 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	5.0 days	Singapore 159941

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2023)
Parts:	M1-MPV	BMW 216I 1.5 GRAN TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA4712G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*BOOTLID	Bent	1,257.95 FS	*1,257.95 FS
3	1		*REAR BUMPER CARRIER	Bent	490.70 FS	*490.70 FS
4	1		*LEFT PROTECT	Not Necessary	11.45 FS	*- FS
5	1		*RIGHT PTOTEC	Not Necessary	11.45 FS	*- FS
6	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	43.95 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	1,088.30 FS	*1,088.30 FS
8	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.65 FS	*- FS
9	1		*LETTERING 216 I	Necessary	65.60 FS	*65.60 FS
10	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
11	1		*PLAQUE 74MM	Necessary	72.85 FS	*72.85 FS
12	1		*STRIKER BOOT LID	Not Necessary	60.95 FS	*- FS
13	1		*LOCK TRUNK LID	Not Necessary	198.70 FS	*- FS
14	1		*ACTUATION UNIT	Not Necessary	624.45 FS	*- FS
15	1		*SPINDLE DRIVE	Not Necessary	399.40 FS	*- FS
16	1		*REAR WINDOW (ESG)	Not Necessary	630.20 FS	*- FS
17	1		*REAR BUMPER TRIM STRIP CHROM	Cracked	97.90 FS	*97.90 FS
18	8		*HOOK AND LOOP FASTENER	Not Necessary	20.00 FS	*- FS
19	1		*LOADING SILL COVER (ANTHRAZIT)	Not Necessary	115.05 FS	*- FS
20	1		*BOOTLID SEALING	Not Necessary	146.70 FS	*- FS
21	2		*ULTRASONIC SENSOR PHYTONIC BLUE (WC)	Not Necessary	772.00 FS	*- FS
22	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	21.20 FS	*- FS
23	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
24	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
25	1		*(DG/SL) ADHRSIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
26	4		*EXPANDING NUT	Necessary	4.20 FS	*4.20 FS
27	10		*BUMP STOP	Necessary	34.50 FS	*34.50 FS
Total Parts (\$\$)					6,698.85	3,510.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	504.00	504.00
2	REPLACE REAR BOOT LID ,REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC TO CARRY OUT ACCIDENT REPAIRING WORKS	New	2,550.00	1,700.00
3	PAINTING REAR BUMPER AND REAR BOOT LID	New	1,923.00	1,826.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
6	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
7	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
8	TO SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
9	TO SUPPLY REAR EMBOSS NUMBER PLATE	New	83.00	0.00
10	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	257.00
11	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
Gross Labour Cost (\$\$)			6,983.00	5,384.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >