

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012825/KVY3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00003172200

Claimant Vehicle No : SKG369U **Insured Vehicle No :** SKU6707P

Date of Loss: 22/12/2022 Nature of Claim: TP Claim No: SNM22D209234/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG369U**

Make & Model: MERCEDES-BENZ CLA180, 1.6 (A) Engine No: 27091031923189

Reg. Date: 07/01/2020 (Man. Year: 2019) Chassis No: WDC1569422J669113

Colour: Metallic Grey Odometer: 80481 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,814.29	7,641.94	2,172.35	22.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,260.00	1,040.00	45.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,114.29	8,901.94	3,212.35	26.52
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	12,114.29	7,000.00	5,114.29	42.22

INSPECTION

Date of Assignment: 23/12/2022

Date Inspected: 27/12/2022 Inspected At: Poon Siang Seow (HQ)
160 Sin Ming Drive, #05-13 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG369U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RIGHT	Bent	991.41 F	*991.41 FL
2	1		*FRONT FENDER ARC GARNISH	Dented / Cut	218.77 F	*218.77 FL
3	1		*WHEEL RIM (LOCAL REPAIR)	Scratched	580.12 FS	*80.00 FS
4	1		*FRONT DOOR	Bent	2,249.10 F	*1,794.00 FL
5	1		*FRONT DOOR CHANNEL	Serviceable	123.11 F	*- FL
6	1		*FRONT DOOR RUBBER	Necessary	234.20 F	*234.20 FL
7	1		*FRONT DOOR POWER MOTOR AND GEAR	Distorted / Jammed	631.68 F	*631.68 FL
8	1		*ROCKER GARNISH	Dented / Cut	831.80 F	*745.00 FL
9	1		*REAR DOOR	Bent	1,820.10 F	*1,820.10 FL
10	1		*REAR DOOR RUBBER	Necessary	234.20 F	*234.20 FL
11	1		*REAR DOOR STICKER	Necessary	80.00 F	*80.00 FL
12	20		*DOOR RIVET	Necessary	90.00 F	*90.00 FL
13	1		*REAR FENDER ARC GARNISH	Cut	229.80 F	*229.80 FL
14	1		*FRONT RIGHT DOOR LOCK	Dented	650.00 F	*483.00 FL
15	1		*FRONT DOOR RIGHT BOARD	Mtg Cracked	850.00 F	*850.00 FL
					Sub Total (S\$)	9,814.29 8,482.16
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 840.22
					Total Parts (S\$)	9,814.29 7,641.94

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	100.00	0.00
2	PANEL BEATING	New	1,200.00	600.00
3	SPRAY PAINTING	New	1,000.00	660.00
Gross Labour Cost (S\$)			2,300.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >