

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012827/UVY3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00048282201
Claimant Vehicle No :	GBB28L	Insured Vehicle No :	SJN8635Z
Date of Loss:	17/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209116/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB28L		
Make & Model:	VOLKSWAGEN CADDY, 1.4 MAXI TSI AT SAJHK5 (A)	Engine No:	DFS220522
Reg. Date:	22/08/2017 (Man. Year: 2017)	Chassis No:	WV1ZZZ2KZXH160946
Colour:	White	Odometer:	169244 km
Engine Capacity:	1968 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,918.52	4,281.36	1,637.16	27.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,470.00	660.00	30.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,048.52	5,751.36	2,297.16	28.54
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	8,048.52	4,600.00	3,448.52	42.85
+ GST 8.00/8.00% (S\$)	643.88	368.00	275.88	42.85
Nett Amount (S\$)	8,692.40	4,968.00	3,724.40	42.85

INSPECTION

Date of Assignment:	23/12/2022	
Date Inspected:	10/04/2023	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 May 2023)	
Parts:	N/A	VOLKSWAGEN CADDY 1.4 MAXI TSI AT SAJHK5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB28L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SLIDING DOOR -RH	Dented / Bent	3,142.95 FL	*2,650.00 FL
2	1		*REAR SLIDING DOOR PROTECTOR-RH	Grazed	151.55 FL	*151.55 FL
3	1		*ROCKER PANEL -RH	Dented / Bent	2,073.45 FL	*1,873.95 FL
4	1		*REAR TYRE RIM HUPCAP -RH	Missing	59.35 FL	*59.35 FL
5	1		*REAR BUMPER	Repair	786.10 FL	*- FL
6	1		*REAR BUMPER SIDE HOLDER -RH	Not Necessary	55.75 FL	*- FL
7	1		*REAR RIM -RH	Serviceable	273.65 FL	*- FL
8	1		*SEALANT (SLIDING DOOR)	Necessary	20.00 FS	*20.00 FS
9	5		*SPONGE TAPE (SLIDING DOOR)	Not Necessary	10.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					6,572.80	4,754.85
- List Item Discount on L Items 10.00/10.00% (\$\$)					654.28	473.49
Total Parts (\$\$)					5,918.52	4,281.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,CUT /WELD ROCKER PANEL,REMOVE,REPLACE ACCIDENT PARTS	New	700.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	600.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO REMOVE,REPLACE R/H SLIDING DOOR GLASS	New	80.00	80.00
5	TO REMOVE ,TRANSFER DOOR AND DOOR FITTINGS	New	80.00	50.00
6	TUFFKOTE	New	60.00	50.00
7	TO REMOVE ,TRANSFER REAR BUMPER SENSOR	New	100.00	40.00
8	TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	80.00	0.00
9	TO RESET CHECK LIGHT	New	200.00	30.00
Gross Labour Cost (S\$)			2,130.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >