

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012836/UYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210063173-01
Claimant Vehicle No :	GBL2696S	Insured Vehicle No :	SNA6223M
Date of Loss:	22/12/2022	Nature of Claim:	TP
		Claim No:	1662244584SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL2696S	Engine No:	HR16179789D
Make & Model:	NISSAN NV200, 1.6 DX (A)	Chassis No:	VM20163010
Reg. Date:	22/04/2021 (Man. Year: 2020)	Odometer:	77441 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,026.47	2,839.20	1,187.27	29.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	810.00	650.00	44.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,486.47	3,649.20	1,837.27	33.49
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	5,486.47	2,900.00	2,586.47	47.14
+ GST 8.00/8.00% (S\$)	438.92	232.00	206.92	47.14
Nett Amount (S\$)	5,925.39	3,132.00	2,793.39	47.14
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,432.00		

INSPECTION

Date of Assignment:	04/01/2023		
Date Inspected:	04/01/2023	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented/ Bent	2,135.60 FN	*1,978.40 FN
2	1		*REAR TAILGATE LOCK	Serviceable	307.70 FN	*- FN
3	1		*REAR TAILGATE WEATHERSTRIP RUBBER	Not Necessary	95.40 FN	*- FN
4	1		*REAR BUMPER	Deformed	989.70 FN	*632.70 FN
5	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FN	*35.00 FN
6	1		*END PANEL (OUTER)	Repair	198.00 FN	*- FN
7	1		*END PANEL TOP GARNISH	Not Necessary	90.00 FN	*- FN
8	1		*REAR TAILGATE NISSAN EMBLEM	Necessary	70.00 FN	*70.00 FN
9	1		*REAR TAILGATE NV200 EMBLEM	Necessary	101.90 FN	*101.90 FN
10	1		*REAR TAILGATE VANETTE EMBLEM	Necessary	70.00 FN	*70.00 FN
11	1		*REAR W/S SEALANT	Necessary	40.00 FS	*40.00 FS
12	1		*SET REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	4,438.30	3,128.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	411.83	288.80
Total Parts (S\$)	4,026.47	2,839.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	480.00	300.00
2	LABOUR CHARGE	New	780.00	350.00
3	LABOUR R&R REAR WINDSCREEN	New	120.00	120.00
4	LABOUR CHARGE REVERSE SENSOR	New	80.00	40.00
Gross Labour Cost (\$\$)			1,460.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >