

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22012837/UYA3Q2**Date:** 04/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100424785
Claimant Vehicle No :	SLT3914X	Insured Vehicle No :	SKU7277G
Date of Loss:	23/12/2022	Nature of Claim:	TP
		Claim No:	4724564102SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3914X		
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Engine No:	M15AY501701
Reg. Date:	28/11/2022 (Man. Year: 2022)	Chassis No:	JTDBBBA300L000232
Colour:	Black	Odometer:	1885 km
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,062.12	4,299.27	10,762.85	71.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	1,730.00	2,010.00	53.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,802.12	6,029.27	12,772.85	67.93
Approved Total (Overridden) (\$\$)		4,800.00		
Nett Amount (\$\$)	18,802.12	4,800.00	14,002.12	74.47
+ Car Rental (5.0 x \$S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		26.75		
Nett Liability (\$\$)		5,326.75		

INSPECTION

Date of Assignment:	23/12/2022	
Date Inspected:	27/12/2022	Inspected At: SPEEDWERKZ PTE LTD (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 147807
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	2,249.00 FL	*1,766.10 FL
2	1		*REAR BOOT LID BOARD	Not Necessary	415.00 FL	*- FL
3	1		*REAR BOOT LID ABSORBER HOLDER	Not Necessary	530.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Twisted	389.00 FL	*389.00 FL
5	1		*REAR BOOT LID INNER LOCK	Bent / Damaged	398.00 FL	*398.00 FL
6	1		*REAR BOOT LOCK CATCH	Not Necessary	65.00 FL	*- FL
7	2		*REAR BOOT HINGE	Not Necessary	178.00 FL	*- FL
8	1		*REAR BOOT CENTRE GARNISH	Not Necessary	402.00 FL	*- FL
9	1		*REAR BOOTLID LOGO	Not Necessary	675.30 FL	*- FL
10	1		*REAR BOOT EMBLEM (HYBRID)	Necessary	49.60 FL	*49.60 FL
11	1		*REAR END PANEL INNER	Repair	765.30 FL	*- FL
12	1		*REAR END PANEL OUTER	Badly Dented / Bent	895.50 FL	*755.10 FL
13	1		*REAR END PANEL TOP GARNISH	Twisted	230.80 FL	*230.80 FL
14	2		*REAR TAIL LAMP	Not Necessary	971.00 FL	*- FL
15	2		*REAR TAIL LAMP PANEL	Not Necessary	250.00 FL	*- FL
16	2		*REAR FENDER INNER GARNISH	Not Necessary	188.50 FL	*- FL
17	2		*REAR FENDER DUST COVER	Not Necessary	112.60 FL	*- FL
18	1		*REAR TOOL TRAY TOP COVER	Not Necessary	198.00 FL	*- FL
19	1		*REAR SPARE TYRE PANEL	Repair	1,012.20 FL	*- FL
20	1		*REAR SPARE TYRE PANEL TOP COVER BOARD	Not Necessary	298.50 FL	*- FL
21	2		*REAR SPARE TYRE TOOL TRAY	Not Necessary	302.60 FL	*- FL
22	1		*REAR BUMPER	Dented / Deformed	1,964.00 FL	*1,355.10 FL
23	2		*REAR BUMPER BRACKET	Not Necessary	96.40 FL	*- FL
24	2		*REAR BUMPER REFLECTOR	Not Necessary	226.40 FL	*- FL
25	2		*REAR NUMBER PLATE LAMP	Not Necessary	151.60 FL	*- FL
26	1		*REAR LOCK ANTENNA	Cracked	284.00 FL	*284.00 FL
27	2		*REAR BUMPER REVERSING SENSOR HOLDER	Not Necessary	97.00 FL	*- FL
28	2		*REAR BUMPER REVERSING SENSOR	Shorted	427.50 FS	*200.00 FS
29	1		*REAR WINDSCREEN GLASS	Not Necessary	1,860.00 FL	*- FL
30	1		*REAR EXHAUST PIPE	Not Necessary	987.00 FL	*- FL
31	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	97.20 FL	*- FL
32	1		*REAR WINDSCREEN MOULDING	Necessary	1,860.00 FL	*118.00 FL
33	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	12		*REAR TAILGATE INNER BOARD CLIP	Not Necessary	60.00 FS	*- FS
35	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
36	6		*REAR END PANEL TOP GARNISH	Not Necessary	30.00 FS	*- FS
37	1		*REAR REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
38	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,612.00	5,635.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,549.88	1,336.43
Total Parts (\$\$)	15,062.12	4,299.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	20.00
2	TO APPLY ANTI RUST CHEMICAL	New	150.00	60.00
3	REMOVE AND REFIX UPHOLSTERY AND CUSHION SEAT	New	280.00	80.00
4	REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
5	REMOVE AND REPLACE REAR BUMPER SENSOR	New	180.00	50.00
6	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,600.00	600.00
7	TO SPRAY PAINTING AND ETC	New	1,200.00	800.00
Gross Labour Cost (S\$)			3,740.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >