

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22012838/UPA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001052244
Claimant Vehicle No :	FBK1771U	Insured Vehicle No :	SMN2513X
Date of Loss:	21/12/2022	Nature of Claim:	TP
		Claim No:	202222009064

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK1771U	Engine No:	N522E036091
Make & Model:	YAMAHA FZ8S, 779cc	Chassis No:	JYARN25F000000758
Reg. Date:	13/04/2015 (Man. Year: 2014)	Odometer:	29101 km
Colour:	Black		
Engine Capacity:	779 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	180/55Z R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,349.00	5,699.70	4,649.30	44.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,522.00	880.00	642.00	42.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,871.00	6,579.70	5,291.30	44.57
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	11,871.00	5,000.00	6,871.00	57.88
+ GST 8.00/8.00% (S\$)	949.68	400.00	549.68	57.88
Nett Amount (S\$)	12,820.68	5,400.00	7,420.68	57.88
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Medical Costs (S\$)		45.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,547.00		

INSPECTION

Date of Assignment:	23/12/2022	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	27/12/2022 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	5.0 days	Singapore 533758

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jul 2023)	
Parts:	N/A	YAMAHA FZ8S 779cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK1771U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR HANDLE	Bent	91.00 F	*91.00 FL
2	1		*BEARING SWINGARM 2	Not Necessary	38.00 F	*- FL
3	1		*BEARING SWINGARM 3	Not Necessary	30.00 F	*- FL
4	1		*BELLY PAN (AFTERMARKET)	Cracked	376.00 F	*376.00 FL
5	1		*BOLT CAP	Bent	310.00 F	*310.00 FL
6	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	230.00 F	*230.00 FL
7	2		*BOX SIDE (GIVI) E22N (BLACK)	Cut / Broken	800.00 F	*800.00 FL
8	1		*BUSH SWING ARM	Not Necessary	77.00 F	*- FL
9	1		*COVER 5	Cut	184.00 F	*184.00 FL
10	1		*COVER BRACKET FOOTREST FRONT	Cut	17.00 F	*17.00 FL
11	1		*COVER MAGNETO ASSY	Cut	121.00 F	*121.00 FL
12	1		*COVER PEDAL SHIFT	Torn	14.00 F	*14.00 FL
13	1		*COVER TAIL REAR	Cut	271.00 F	*271.00 FL
14	1		*COVER TANK CENTER	Cut	310.00 F	*310.00 FL
15	1		*COWLING FRONT ASSY	Cut	800.00 F	*800.00 FL
16	4		*DAMPER COVER FUEL TANK 2	Not Necessary	24.00 F	*- FL
17	1		*DAMPER FUEL TANK	Not Necessary	6.00 F	*- FL
18	1		*DAMPER RUBBER 1	Not Necessary	6.00 F	*- FL
19	1		*FOOTREST FRONT ASSY RH	Bent	73.00 F	*73.00 FL
20	1		*GASKET CRANKCASE COVER	Necessary	12.00 F	*12.00 FL
21	1		*HANDGUARD (AFTERMARKET)	Cut	150.00 F	*150.00 FL
22	2		*HOLDER DAMPER LH	Twisted	62.00 F	*62.00 FL
23	1		*LAMP SIGNAL FRONT RH	Cut	33.00 F	*33.00 FL
24	1		*LAMP SIGNAL REAR LH	Cracked	34.00 F	*34.00 FL
25	1		*LOGO (YAMAHA) (LARGE)	Necessary	35.00 F	*35.00 FL
26	1		*MIRROR LH	Scratched	136.00 F	*136.00 FL
27	1		*MIRROR RH	Cut	147.00 F	*147.00 FL
28	1		*MUFFLER ASSY	Dented / Bent	1,555.00 F	*1,555.00 FL
29	1		*O-RING	Necessary	5.00 F	*5.00 FL
30	1		*O-RING (FUEL PUMP)	Necessary	38.00 F	*38.00 FL
31	1		*PANEL INNER RH	Cut	140.00 F	*140.00 FL
32	1		*PEDAL BRAKE	Bent	63.00 F	*63.00 FL
33	1		*PLUG	Torn	17.00 F	*17.00 FL
34	1		*SEAL 3	Not Necessary	11.00 F	*- FL
35	1		*SEAL 4	Not Necessary	11.00 F	*- FL
36	1		*SEAL 5	Not Necessary	11.00 F	*- FL
37	1		*SEAL 6	Not Necessary	11.00 F	*- FL
38	1		*SEAL COVER FUEL TANK	Not Necessary	5.00 F	*- FL
39	1		*SEAL GUARD	Torn	115.00 F	*115.00 FL
40	1		*SLIDER FRAME (MOTOVATION)	Cut	150.00 F	*150.00 FL
41	1		*STICKER COVER SIDE RH	Necessary	34.00 F	*34.00 FL
42	1		*STICKER WARNING YAMAHA	Necessary	10.00 F	*10.00 FL
43	1		*SWING ARM	Repair	2,138.00 F	*- FL
44	2		*WASHER THRUST SWINGARM	Not Necessary	38.00 F	*- FL
45	1		*TANK FUEL	Repair	1,610.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	10,349.00	6,333.00
				- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	633.30
				Total Parts (S\$)	10,349.00	5,699.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,242.00	600.00
2	REPAIR & SPRAY PAINTING FUEL TANK	New	280.00	280.00
Gross Labour Cost (S\$)			1,522.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >