



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 9405H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT VISOR	SERVICEABLE	67.50	-
1	FRONT CENTRE PANEL	NOT NECESSARY	145.00	-
1	FRONT COWLING STAY	NOT NECESSARY	89.60	-
2	BODY COWLING LH/RH @ 167.50/-	O/S CUT (1PC ONLY)	335.00	167.50
1	BODY COWLING INNER PANEL (MAT BLACK)	HDR CRACKED	121.50	105.00
2	FRONT FORK ASSY @ \$446.50/-	BENT	893.00	800.00
1	FORK UNDER BRACKET COMPLETE	SERVICEABLE	205.00	-
1	FRONT WHEEL RIM	NOT NECESSARY	380.00	-
1	FOOT STEP BOARD RH	CUT	120.50	120.50
1	FOOTREST BOARD LOWER SIDE COVER RH	CUT	128.60	128.60
1	MUFFLER PROTECTOR	CUT	110.00	110.00
	LESS 10% DISCOUNT		-259.57	-143.16
			2,336.13	1,288.44
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET STEERING CONE & BEARING (SN)	NECESSARY	210.00	80.00
1	SET BODY STICKER (SN)	NECESSARY	150.00	80.00
			360.00	160.00
	<b><u>LABOUR</u></b>			
	CHASSIS FRAME ALIGN.		550.00	200.00
	WORKMANSHIP.		500.00	300.00
			1,050.00	500.00
	<b>GRAND TOTAL</b>		<b>3,746.13</b>	<b>1,948.44</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,550.00</b>

Report Ref No. CS3/ASM22003936/Rqy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.