



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 5050S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER-BUMPER (SN)	TO REPAIR SEE LABOUR	2,633.30	-
1	BRACKET-FENDR/BUMPR (SN)	NOT NECESSARY	83.20	-
1	PANEL-FENDER LH (SN)	TO REPAIR SEE LABOUR	1,496.80	-
1	LINER-WHEELARCH LH (SN)	NOT NECESSARY	416.80	-
1	HEADLAMP LH (SN)	NOT NECESSARY	12,795.80	-
1	WHEEL-ROAD-ALLOY (SN)	SCRATCHED	4,642.90	4,178.61
1	BADGE (SN)	NOT NECESSARY	176.30	-
			22,245.10	4,178.61
	<b><u>LABOUR</u></b>			
	TO REPLACE FRT BUMPER, FRT FENDER LH, HEADLAMP LH, ETC. INCLUSIVE OF THE REPAIR OF COVER-BUMPER AND PANEL-FENDER LH.		3,000.00	2,600.00
	TO SPRAY FRT BUMPER, FRT FENDER LH.		2,500.00	2,000.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	621.00
	TO FOCUS HEADLAMP.	NOT NECESSARY	207.00	-
	TO REPLACE LHF RIM.		50.00	50.00
	WHEEL ALIGNMENT.		280.00	280.00
			6,658.00	5,551.00
	<b>GRAND TOTAL</b>		<b>28,903.10</b>	<b>9,729.61</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>9,729.61</b>

Report Ref No. CS/FCI22012847/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.