

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURANCE BHD			Ref:	CS3/LPC22012849/Gny3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	02/02/2023		
				Code:	LPC2	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XB 9639D	Veh. Inspected		GBE 5621A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/23/VC05/026746	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		22/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA 150	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTFAT35Y40K205554	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	GRENLANDER		6 mm	
	L/H Front Tyre	195 R15	GRENLANDER		6 mm	
	R/H Rear Tyre	155 R12 (D)	CONDOR		6/6 mm	
	L/H Rear Tyre	155 R12 (D)	CONDOR		6/6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS O/S AND N/S BOD COLLISION.	SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, SODY. THE UNDERCARRIAGE AFFECTED DUE TO				
5.	5. General Information					
	Accident Date	20/12/2022	Inspect Date /	Time	27/12/2022 (12:43 PM)	
	Survey held at	A T PERFORMANCE				
		160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22012849/Gny3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor