

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012850/AGNY3M4**Date:** 13/06/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30002443350
Claimant Vehicle No :	SJL6151B	Insured Vehicle No :	XD7722Z
Date of Loss:	23/12/2022	Nature of Claim:	TP
		Claim No:	296499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL6151B	Engine No:	G4EE8H192408
Make & Model:	KIA RIO, 1.4 2WD 5DR (M)	Chassis No:	KNADE241296479921
Reg. Date:	04/12/2008 (Man. Year: 2008)	Odometer:	340436 km
Colour:	Black		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,969.25	1,920.87	4,048.38	67.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	1,450.00	1,420.00	49.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,839.25	3,370.87	5,468.38	61.86
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	8,839.25	2,700.00	6,139.25	69.45

INSPECTION

Date of Assignment:	27/12/2022		
Date Inspected:	27/12/2022	Inspected At:	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2023)
Parts:	144	KIA RIO 1.4 2WD 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL6151B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/H FRONT DOOR ASSY	Not Necessary	1,044.20 FL	*- FL
2	1		*R/H FRONT DOOR PROTECTOR	Repair	315.20 FL	*- FL
3	3		*R/H FRONT DOOR BLACK STICKER	Not Necessary	135.00 FL	*- FL
4	1		*R/H REAR DOOR ASSY	Dented	899.40 FL	*899.40 FL
5	2		*R/H REAR DOOR HINGES	Not Necessary	188.40 FL	*- FL
6	1		*R/H REAR DOOR LOCK	Not Necessary	287.60 FL	*- FL
7	1		*R/H REAR DOOR WEATHERSTRIP	Not Necessary	156.20 FL	*- FL
8	1		*R/H REAR DOOR PROTECTOR	Repair	315.20 FL	*- FL
9	1		*R/H REAR DOOR CHECKER	Not Necessary	74.20 FL	*- FL
10	1		*R/H REAR FENDER PANEL	Repair	936.80 FL	*- FL
11	1		*R/H REAR SHOCK ABSORBER	Not Necessary	310.40 FL	*- FL
12	1		*R/H REAR BEARING HUB	Damaged	344.50 FL	*344.50 FL
13	1		*R/H REAR HUB ASSY	Damaged	290.40 FL	*290.40 FL
14	3		*R/H REAR DOOR BLACK STICKER	Necessary	121.50 FS	*60.00 FS
15	1		*R/H SPORT RIM	Cut	480.00 FS	*480.00 FS
16	1		*R/H CENTRE LOWER SIDE SKIP	Repair	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,499.00	2,074.30
- List Item Discount on L Items 10.00/10.00% (S\$)	529.75	153.43
Total Parts (S\$)	5,969.25	1,920.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/RENEW UNDERCARRIES IN REPAIR	New	280.00	80.00
2	TO DISM/REWIRE DAMAGED PORTION	New	120.00	50.00
3	TO COMPLETE WHEEL ALIGNMENT	New	150.00	80.00
4	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,200.00	500.00
5	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	700.00
6	TO SPRAY UNDERCOATING IN REPAIR	New	120.00	40.00
Gross Labour Cost (S\$)			2,870.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >