

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012852/RQY3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00127482202

Claimant Vehicle No : SMK3357P **Insured Vehicle No :** GZ2535R

Date of Loss: 21/12/2022 Nature of Claim: TP Claim No: SNM22D209222/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK3357P**

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 2NRX434715

Reg. Date: 05/04/2019 (Man. Year: 2019) Chassis No: MR2B23F3601172462

Colour: Grey Odometer: 51232 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,542.40	2,711.90	1,830.50	40.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,100.64	7,152.64	3,948.00	35.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,643.04	9,864.54	5,778.50	36.94
+ GST 8.00/8.00% (S\$)	1,251.44	789.16	462.28	36.94
Nett Amount (S\$)	16,894.48	10,653.70	6,240.78	36.94

INSPECTION

Date of Assignment: 23/12/2022

Date Inspected: 16/02/2023 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK3357P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
2	1		*PANEL BONDING AD	Necessary	267.20 FS	*267.20 FS
3	1		*COVER ,RR BUMPER L/C	Deformed	633.90 FS	*633.90 FS
4	10		*PIECE,RR BUMPER	Necessary	49.00 FS	*49.00 FS
5	2		*TAPE ,MOULDING NO	Necessary	121.20 FS	*121.20 FS
6	2		*PAD ,RR BUMPER ,RH	Necessary	26.60 FS	*26.60 FS
7	1		*RETAINER ,RR BUMPER	Not Necessary	186.50 FS	*- FS
8	1		*RETAINER ,RR BUMPER	Not Necessary	186.50 FS	*- FS
9	1		*PANEL SUB-ASSY ,QUAR	Bent	1,089.00 FS	*1,089.00 FS
10	1		*PANEL SUB-ASSY ,FR D	Repair	1,313.90 FS	*- FS
11	1		*MOULDING ,FR DOOR WI	Not Necessary	51.60 FS	*- FS
12	10		*RIVET	Not Necessary	18.00 FS	*- FS
13	10		*RIVET	Not Necessary	24.00 FS	*- FS
14	1		*DAM BACK WINDOW GLA	Necessary	39.50 FS	*39.50 FS
15	1		*DAM BACK WINDOW GLA	Necessary	19.50 FS	*19.50 FS
16	2		*SIKA 182010 SIKA TACK GO(BLA)	Necessary	216.00 FS	*216.00 FS
17	1		*SIKA 207 G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
Total Parts (S\$)					4,542.40	2,711.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY SEALANT	New	100.00	100.00
2	DRILL HOLE AND INSTALL REVERSE SENSOR	New	198.00	198.00
3	CHECK WIRING AND CONDUCT WATER TEST	New	134.64	134.64
4	REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR	New	396.00	0.00
5	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	792.00	792.00
6	R/I REAR WINDSCREEN GLASS TO FAC REPAIR	New	594.00	594.00
7	TO RESET ECU AND REPROGRAMME	New	198.00	198.00
8	REPLACE ACC DAMAGED PARTS	New	4,752.00	3,168.00
9	RESPRAY ACC AFFECTED AREAS	New	3,936.00	1,968.00
Gross Labour Cost (\$\$)			11,100.64	7,152.64

Report was unsubmitted during this print-out.

< END OF ESTIMATES >