

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012858/AVY3M4**Date:** 09/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00057902200		
Claimant Vehicle No :	SFD1069D	Insured Vehicle No :	SLS1909E		
Date of Loss:	25/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209275/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFD1069D	Engine No:	L15B72451273
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFC1660HT000086
Reg. Date:	19/05/2017 (Man. Year: 2017)	Odometer:	77435 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,572.40	7,465.84	2,106.56	22.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	3,040.00	920.00	23.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,532.40	10,505.84	3,026.56	22.37
Approved Total (Overridden) (S\$)		8,400.00		
Nett Amount (S\$)	13,532.40	8,400.00	5,132.40	37.93

INSPECTION

Date of Assignment:	27/12/2022		
Date Inspected:	27/12/2022	Inspected At:	Jec Autoservice (HQ) 1 Kaki Bukit Ave 6 #02-11 Autobay Singapore 417883
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFD1069D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	647.70 F	*647.70 FL
2	1		*REAR BUMPER SIDE HOLDER LH	Damaged	24.50 F	*24.50 FL
3	1		*REAR BUMPER SIDE GRILLE LH	Cut	171.60 F	*171.60 FL
4	1		*REAR BUMPER SIDE GRILLE REFLECTOR LH	Cracked	30.40 F	*30.40 FL
5	1		*REVERSE SENSOR	Damaged	261.40 F	*261.40 FL
6	1		*REAR END PANEL	Dented	388.20 F	*388.20 FL
7	1		*TAILLAMP LH	Cracked	330.50 F	*330.50 FL
8	1		*TAILLAMP PANEL LH	Buckled	168.60 F	*168.60 FL
9	1		*REAR LH FENDER	Distorted	970.80 F	*970.80 FL
10	1		*REAR LH FENDER INNER TRIM	Crumpled	268.20 F	*268.20 FL
11	1		*REAR LH FENDER INNER SHIELD	Torn	165.90 F	*165.90 FL
12	1		*REAR LH FENDER AIR VENT	Distorted	55.90 F	*55.90 FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	156.70 F	*156.70 FL
14	1		*ROCKER PANEL SIDE SKIRTING RH	Deformed	640.80 F	*640.80 FL
15	1		*REAR LH LOWER ARM	Bent	384.40 F	*384.40 FL
16	1		*REAR LH KNUCKLE ARM	Bent	388.50 F	*388.50 FL
17	1		*REAR LH WHEEL HUB C/W BEARING	Damaged	290.40 F	*290.40 FL
18	1		*REAR LH CONTROL ARM	Bent	234.70 F	*234.70 FL
19	1		*REAR LH STAY ARM	Bent	240.40 F	*240.40 FL
20	1		*REAR LH TRAILING ARM	Bent	349.40 F	*349.40 FL
21	1		*REAR LH SHOCK ABSORBER	Bent	344.10 F	*344.10 FL
22	1		*HORN	Not Necessary	98.40 F	*- FL
23	1		*HORN BRACKET	Bent	39.40 F	*39.40 FL
24	1		*REAR EXHAUST PIPE	Dented	687.50 F	*687.50 FL
25	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	34.20 F	*- FL
26	1		*REAR EXHAUST PIPE GASKET	Necessary	30.40 F	*30.40 FL
27	1		*SPEED SENSOR	Damaged	349.40 F	*349.40 FL
28	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*REAR LH FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*REAR LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
33	1		*REAR LH WHEEL RIM	Cut	880.00 FS	*580.00 FS
34	1		*REAR LH TYRE	Cut	350.00 FS	*200.00 FS
35	1		*ROCKER PANEL SIDE SKIRTING LOWER GARNISH RH	Deformed	380.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,572.40	8,989.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,523.96
Total Parts (\$\$)	9,572.40	7,465.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	1,300.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
7	TO REMOVE EXHAUST PIPE	New	150.00	80.00
8	TO REMOVE UPHOLSTERY	New	150.00	80.00
9	TO REMOVE REAR UNDERCARRIAGE	New	380.00	220.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			3,960.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >