

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS22012872/UWY3M4**Date:** 13/03/2023**REFERENCE**

Insured/Claimant:	VALIANT KHONG FARN BING	Policy No:	SP2003638569
Date of Loss:	18/12/2022	Nature of Claim:	OD
		Claim No:	202222009078/JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV2073T	Engine No:	PE10527205
Make & Model:	MAZDA 5 WAGON, 2.0 EU6 (A)	Chassis No:	JM6CW1071H0126678
Reg. Date:	26/12/2017 (Man. Year: 2017)	Odometer:	179416 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,120.60	8,682.30	6,438.30	42.58
Miscellaneous Items	275.00	35.00	240.00	87.27
Labour	4,430.00	2,220.00	2,210.00	49.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,825.60	10,937.30	8,888.30	44.83
Approved Total (Overridden) (S\$)		7,650.00		
- Excess (S\$)	0.00	3,000.00	-3,000.00	
(S\$)	19,825.60	4,650.00	15,175.60	76.55
+ GST 7.00/7.00% (S\$)	1,387.79	325.50	1,062.29	76.55
Nett Amount (S\$)	21,213.39	4,975.50	16,237.89	76.55

INSPECTION

Date of Assignment:	24/12/2022	Present Location:	SME Motor Pte Ltd (Kaki Bukit) SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883
Date Inspected:	27/12/2022	Inspected At:	
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Mar 2023)	
Parts:	N/A	MAZDA 5 WAGON 2.0 EU6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV2073T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	580.00 F	*580.00 F
2	1		*FRT BONNET SEAL (WITH CLIPS) (WCP)	Twisted	55.00 F	*55.00 F
3	1		*FRT BONNET INSULATOR (WCP)	Not Necessary	135.00 F	*- F
4	8		*INSULATOR CLIPS (WCP)	Necessary	20.00 F	*20.00 F
5	2		*FRT BONNET HINGE (WCP)	Bent	90.00 F	*90.00 F
6	1		*FRT BONNET LOCK (WCP)	Twisted	115.00 F	*115.00 F
7	1		*FRT BUMPER (WCP)	Distorted	480.00 F	*480.00 F
8	2		*FRT BUMPER RETAINER (WCP)	Cracked/Necessary	50.00 F	*50.00 F
9	10		*FRT BUMPER CLIPS (WCP)	Necessary	25.00 F	*25.00 F
10	1		*FRT BUMPER INNER SPONGE (WCP)	Not fitted	105.00 F	*- F
11	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	350.00 F	*350.00 F
12	1		*FRT BUMPER INNER BASE TOP (WCP)	Not Necessary	220.00 F	*- F
13	1		*FRT BUMPER LOGO (WCP)	Necessary	45.00 F	*45.00 F
14	1		*FRT BUMPER CTR GRILLE (WCP)	Torn	380.00 F	*380.00 F
15	1		*FOG LAMP LH (WCP)	Not Necessary	180.00 F	*- F
16	1		*FOG LMAP GARNISH LH (WCP)	Twisted	55.00 F	*55.00 F
17	1		*HEADLAMP (WCP)	N/s Broken/ O/s Serviceable	1,360.00 F	*680.00 F
18	1		*HEADLAMP LOWER BRACKET (WCP)	N/s Cracked/ O/s Not Necessary	90.00 F	*45.00 F
19	1		*HEADLAMP SUPPORT PANEL (WCP)	Cracked	380.00 F	*380.00 F
20	1		*BRACE PANEL (WCP)	Not Necessary	38.00 F	*- F
21	1		*AIRCON CONDENSER (WCP)	Bent/Punctured	480.00 F	*480.00 F
22	1		*RADIATOR (WCP)	Bent/Punctured	500.00 F	*500.00 F
23	1		*RADIATOR FAN ASSY (WCP)	Cracked/Jammed	680.00 F	*680.00 F
24	1		*AIR DUCT (WCP)	Not Necessary	115.00 F	*- F
25	1		*AIR CLEANER BOX ASSY (WCP)	Cracked	225.00 F	*225.00 F
26	1		* ISTOP CONTROL UNIT RH (CONVERTER) (WCP)	Not Necessary	420.00 F	*- F
27	1		*FRT FENDER LH (WCP)	Buckled	235.00 F	*235.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRT FENDER INNER COWLING LH (WCP)	Torn	195.00 F	*195.00 F
29	10		*INNER COWLING CLIPS (WCP)	Necessary	20.00 F	*20.00 F
30	1		*FRT BUMPER UNDER COVER (WCP)	Not Necessary	195.00 F	*- F
31	1		*FRT FENDER TOP CORNER GARNISH LH (WCP)	Repair	40.00 F	*- F
32	1		*SIDE SKIRT LH (WCP) (TORN) (NOT CONSISTENT WITH THE IMPACT)	Old Damaged	580.00 F	*- F
33	15		*SIDE SKIRT CLIPS (WCP)	Not Necessary	75.00 F	*- F
34	1		*WIPPER GARNISH LH (WCP)	Cut	130.00 F	*130.00 F
35	1		*WPPER CORNER GARNISH LH (WCP)	Twisted	28.00 F	*28.00 F
36	1		*FRT SHOCK ABSORBER LH (WCP)	Bent	350.00 F	*350.00 F
37	1		*FRT KNUCKLE ARM LH (WCP)	Bent	280.00 F	*280.00 F
38	1		*FRT KNUCKLE BEARING LH (WCP)	Necessary	115.00 F	*115.00 F
39	1		*FRT LOWER ARM LH (WCP)	Bent	210.00 F	*210.00 F
40	1		*FRT ANTI ROLL BAR LINK LH (WCP)	Not Necessary	95.00 F	*- F
41	1		*FRT RACK END LH (WCP)	Not Necessary	115.00 F	*- F
42	1		*FRT TIE ROD END LH (WCP)	Not Necessary	115.00 F	*- F
43	1		*STEERING RACK (WCP)	Not Necessary	850.00 F	*- F
44	1		*STEERING CROSSMEMBER (WCP)	Not Necessary	1,750.00 F	*- F
45	1		*FRT LH SPORT RIM (ORI) (WCP)	Warped	580.00 F	*580.00 F
46	1		*LH ENGINE MOUNTING (WCP)	Torn	185.00 F	*185.00 F
47	1		*RH ENGINE MOUNTING (WCP)	Torn	210.00 F	*210.00 F
48	1		*REAR ENGINE MOUNTING (WCP)	Torn	120.00 F	*120.00 F
49	4		*AUTO OIL (WCP)	Not Necessary	100.00 F	*- F

F=Franchise part.

Sub Total (\$)	13,746.00	7,893.00
+ Margin on L,N Items 10.00/10.00% (\$)	1,374.60	789.30
Total Parts (\$)	15,120.60	8,682.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT LH TYRE Serviceable	235.00	0.00
2	1	FRT NUMBER PLATE Broken	40.00	35.00
Sub Total (S\$)			275.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	New	350.00	150.00
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	180.00	180.00
5	REMOVE & REFIX ENGINE	New	350.00	0.00
6	4 WHEEL ALIGNMENT	New	100.00	70.00
7	REPROGRAMME ISTOP CONTROL UNIT	New	500.00	0.00
8	REMOVE & REFIX FUSE BOX LH	New	120.00	0.00
9	LABOUR CHARGE	New	1,400.00	800.00
10	SPRAY PAINTING	New	1,300.00	900.00
Gross Labour Cost (S\$)			4,430.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >