

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22012873/AQY3Q2**Date:** 30/03/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SKG6865P **Insured Vehicle No :** SJV4174X

Date of Loss: 24/12/2022 Nature of Claim: TP Claim No: DMPC2200660H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG6865P**

Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030676469

Reg. Date: 11/08/2016 (Man. Year: 2016) Chassis No: WDD2050402R195206

Colour: Grey Odometer: 86326 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,721.90	13,592.90	8,129.00	37.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.00	2,310.00	4,030.00	63.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,061.90	15,902.90	12,159.00	43.33
Approved Total (Overridden) (S\$)		12,700.00		
Nett Amount (S\$)	28,061.90	12,700.00	15,361.90	54.74

INSPECTION

Date of Assignment: 27/12/2022

Date Inspected: 27/12/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts: 143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKG6865P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,191.00 FL	*1,890.00 FL
2	1		*REAR BUMPER CENTRE FRAME	Deformed	232.00 FL	*232.00 FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	88.00 FL	*- FL
4	1		*REAR BUMPER EXHAUST COVER GARNISH	Deformed	138.00 FL	*138.00 FL
5	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,060.00 FL	*530.00 FL
6	6		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	402.00 FL	*120.00 FL
7	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	798.00 FL	*- FL
8	2		*REAR BUMPER CENTER UPPER BRACKET	Cracked	156.00 FL	*156.00 FL
9	1		*REAR BUMPER BOTTOM CENTER GARNISH	Deformed	185.00 FL	*185.00 FL
10	1		*REAR BUMPER LOWER GARNISH	Distorted	285.00 FL	*285.00 FL
11	1		*REAR BUMPER LOWER GARNISH CHROME	Cracked	346.00 FL	*346.00 FL
12	2		*REAR BUMPER UPPER CORNER BRACKET	Cracked	358.00 FL	*358.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Damaged	148.00 FL	*148.00 FL
14	2		*REAR BUMPER LOWER BRACKET (CENTER)	Cracked	130.00 FL	*130.00 FL
15	1		*REAR BUMPER SMART SENSOR CONTROL UNIT	Damaged	374.00 FL	*374.00 FL
16	1		*REAR BUMPER SMART SENSOR	Damaged	169.00 FL	*169.00 FL
17	1		*REAR BUMPER SMART SENSOR C/W CABLE	Not Necessary	279.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Dented	658.00 FL	*658.00 FL
19	2		*REAR FENDER COWLING	Not Necessary	396.00 FL	*- FL
20	2		*REAR FENDER INNER TRIM	Not Necessary	850.00 FL	*- FL
21	2		*REAR FENDER DRAIN GARNISH	Not Necessary	494.00 FL	*- FL
22	2		*TAILLAMP	Cracked	1,524.00 FL	*1,524.00 FL
23	1		*TAILLAMP PANEL LH	Repair	986.00 FL	*- FL
24	1		*BOOTLID	Dented	2,450.00 FL	*2,242.00 FL
25	2		*BOOTLID HINGE	Not Necessary	622.00 FL	*- FL
26	1		*BOOTLID CENTER MOULDING	Necessary	159.00 FL	*159.00 FL
27	1		*BOOTLID LOGO	Necessary	48.00 FL	*48.00 FL
28	1		*BOOTLID EMBLEM C180	Necessary	86.00 FL	*86.00 FL
29	1		*BOOTLID TOP LOCK	Damaged	300.00 FL	*300.00 FL
30	1		*BOOTLID LOWER LOCK	Not Necessary	48.00 FL	*- FL
31	1		*BOOTLID WEATHERSTRIP	Cut	189.00 FL	*189.00 FL
32	1		*BOOTLID NUMBER PLATE LAMP GARNISH	Not Necessary	168.00 FL	*- FL
33	1		*REAR END PANEL	Distorted	1,460.00 FL	*1,260.00 FL
34	1		*REAR END PANEL INNER GARNISH	Cracked	285.00 FL	*285.00 FL
35	1		*REAR FLOOR PANEL TOP BOARD	Deformed	563.00 FL	*563.00 FL
36	1		*REAR FLOOR PANEL MAT	Not Necessary	288.00 FL	*- FL
37	1		*REAR FLOOR WHEEL PANEL	Cracked	643.00 FL	*643.00 FL
38	1		*REAR FLOOR WELL PANEL BOTTOM SIDE GARNISH RH	Torn	165.00 FL	*165.00 FL
39	1		*REAR EXHAUST BOX	Bent	1,630.00 FL	*1,498.00 FL
40	2		*REAR EXHAUST INSULATOR	Not Necessary	392.00 FL	*- FL
41	2		*REAR EXHAUST SIDE INSULATOR	Not Necessary	310.00 FL	*- FL
42	4		*REAR EXHAUST MOUNTING	Not Necessary	388.00 FL	*- FL
43	2		*REAR EXHAUST MOUNTING BRACKET	Not Necessary	150.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR NUMBER PLATE	Bent	80.00 FS	*60.00 FS
45	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
46	1		*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
47	1		*SET REAR BUMPER LOWER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
48	1		*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
49	1		*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
50	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
51	1		*BOOTLID CENTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
52	1		*SET BOOTLID NUMBER PLATE LAMP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
53	1		*BOOTLID EMBLEM C&C	Necessary	120.00 FS	*40.00 FS
54	1		*SET TAILLAMP CLIP	Necessary	50.00 FS	*40.00 FS
55	1		*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
56	1		*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
57	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
58	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
59	1		*SET REAR END PANEL INNER GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
60	1		*SET REAR FLOOR UNDER SIDE GARNISH CLIP RH	Necessary	80.00 FS	*20.00 FS
61	1		*REAR FLOOR WELL PANEL SEALANT	Necessary	180.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,981.00	15,061.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,259.10	1,468.10
Total Parts (\$)	21,721.90	13,592.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	350.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	380.00	60.00
6	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX AND RESET BOOTLID AUTO SYSTEM	New	250.00	60.00
9	REMOVE AND REFIX REAR FLOOR WELL PANEL	New	350.00	60.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	350.00	80.00
11	REAR CHASSIS ALIGNMENT	New	250.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	100.00
Gross Labour Cost (\$\$)			6,340.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >