

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22012875/KQY3E2**Date:** 15/06/2023**REFERENCE**

Insured/Claimant:	JECS SINGAPORE PTE LTD	Policy No:	DMPG22010314
Date of Loss:	22/12/2022	Nature of Claim:	OD Claim No: CDMPG22002765

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKW5737Z</b>		
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Engine No:	27492030608927
Reg. Date:	16/08/2017 (Man. Year: 2016)	Chassis No:	WDD2050422F334314
Colour:	Metallic Black	Odometer:	131108 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/35Z R19	Rear Tyre Size:	245/35Z R19
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,225.00	5,322.50	902.50	14.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	1,100.00	870.00	44.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,195.00</b>	<b>6,422.50</b>	<b>1,772.50</b>	<b>21.63</b>
<b>- Excess (\$\$)</b>	0.00	200.00	-200.00	
<b>(\$\$)</b>	8,195.00	6,222.50	1,972.50	24.07
<b>+ GST 7.00/8.00% (\$\$)</b>	573.65	497.80	75.85	13.22
<b>Nett Amount (\$\$)</b>	<b>8,768.65</b>	<b>6,720.30</b>	<b>2,048.35</b>	<b>23.36</b>

**INSPECTION**

Date of Assignment:	27/12/2022	Present Location:	Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected:	27/12/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2023)
Parts:	143	MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW5737Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH Headlamp (WCP)	Cracked	900.00 F	*900.00 F
2	1		*RH Headlamp Bracket (WCP)	Cracked	140.00 F	*140.00 F
3	1		*Front Bumper (WCP)	Cracked	1,100.00 F	*1,100.00 F
4	1		*Front Bumper Side (WCP)	Cracked	60.00 F	*60.00 F
5	1		*Front Bumper Sponge (WCP)	Cracked	140.00 F	*140.00 F
6	1		*Front Bumper Carier Lower (WCP)	Cracked	120.00 F	*120.00 F
7	1		*Front Bumper Carier Top (WCP)	Cracked	70.00 F	*70.00 F
8	1		*RH Fog Garnish (WCP)	Missing	55.00 F	*55.00 F
9	1		*RH Front Bumper Side Retainer (WCP)	Cracked	20.00 F	*20.00 F
10	1		*Front Console Mounting (WCP)	Bent	190.00 F	*190.00 F
11	1		*Front Bumper Clip (WCP)	Necessary	80.00 FS	*80.00 FS
12	1		*Front Parking Sensor Wire (WCP)	Serviceable	120.00 F	*- F
13	1		*Rivets (WCP)	Not Necessary	80.00 FS	*- FS
14	1		*RH Front FENDER (WCP)	Bent	640.00 F	*640.00 F
15	1		*RH Front Fender UnderShield (Front) (WCP)	Cracked	140.00 F	*140.00 F
16	1		*RH Front Sports Rim AMG R19 (WCP)	Dented	900.00 F	*500.00 FS
17	1		*RH Front Tyre (70%)(WCP)	Cut	430.00 FS	*301.00 FS
18	1		*Front Grille Base (WCP)	Cracked	100.00 F	*100.00 F
19	1		*Front Air Duct (WCP)	Distorted	110.00 F	*110.00 F
20	1		*Bonnet Logo (WCP)	Not Necessary	65.00 F	*- F
21	1		*Front Fender Undershield Clip (WCP)	Necessary	80.00 FS	*80.00 FS
22	1		*RH Front Parking Sensor Corner (WCP)	Cut	180.00 F	*180.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,720.00	4,926.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	505.00	396.50
Total Parts (\$\$)	6,225.00	5,322.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To check wiring and focus headlamp	New	50.00	20.00
2	To transfer tyre to new rim and balacing	New	50.00	20.00
3	Computerise Wheel Alignment	New	120.00	60.00
4	To computer reset electronic functions	New	250.00	150.00
5	To straighten RH front inner panel, bonnet including replacement of parts	New	700.00	450.00
6	To spray paint on bonnet, RH front fender, front bumper	New	800.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,970.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >