

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG22012876/GVY3M4**Date:** 06/02/2023**REFERENCE**

Insured/Claimant:	NG WEE KIEN	Policy No:	1001927715	
Date of Loss:	14/12/2022	Nature of Claim:	OD	Claim No: 294970

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDG1600C</b>		
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)	Engine No:	27492030116328
Reg. Date:	28/02/2014 (Man. Year: 2013)	Chassis No:	WDD2120362A909313
Colour:	Silver	Odometer:	191748 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,081.74	6,217.35	6,864.39	52.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,870.00	2,430.00	56.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,381.74</b>	<b>8,087.35</b>	<b>9,294.39</b>	<b>53.47</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,450.00</b>		
<b>- Excess (\$\$)</b>	700.00	700.00	0.00	0.00
<b>(\$\$)</b>	16,681.74	5,750.00	10,931.74	65.53
<b>+ GST 8.00/8.00% (\$\$)</b>	1,334.54	460.00	874.54	65.53
<b>Nett Amount (\$\$)</b>	<b>18,016.28</b>	<b>6,210.00</b>	<b>11,806.28</b>	<b>65.53</b>

**INSPECTION**

Date of Assignment: 27/12/2022

Date Inspected: 27/12/2022 Inspected At:

Estimated Period of Repair: 6.0 days

Elite Automotive Pte Ltd (HQ)  
280 Woodlands Industrial Park E5, #01-17,  
Harvest@Woodlands  
Singapore 757322

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2023)
Parts:	143	MERCEDES-BENZ E250 2.0 SEDAN (R18) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDG1600C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LHS RIM	Cut	988.72 FL	*988.72 FL
2	1		*FRONT LHS FENDER	Buckled	1,140.53 FL	*1,140.53 FL
3	1		*FRONT LHS DOOR	Bent	1,902.73 FL	*1,902.73 FL
4	1		*LHS SIDE SKIRT	Cut	770.01 FL	*770.01 FL
5	1		*FRONT LHS DOOR WINDOW OUTER CHROME MOULDING	Not Necessary	132.24 FL	*- FL
6	1		*FRONT LHS DOOR WINDOW TOP RUBBERSTRIP	Not Necessary	304.27 FL	*- FL
7	1		*FRONT LHS DOOR WEATHERSTRIP	Necessary	317.05 FL	*317.05 FL
8	1		*REAR LHS DOOR	Repair	1,956.17 FL	*- FL
9	1		*REAR LHS DOOR WEATHERSTRIP	Not Necessary	317.05 FL	*- FL
10	1		*REAR LHS DOOR WINDOW OUTER CHROME MOULDING	Not Necessary	160.14 FL	*- FL
11	1		*REAR LHS DOOR WINDOW OUTER TOP RUBBERSTRIP	Not Necessary	469.26 FL	*- FL
12	1		*REAR LHS FENDER	Repair	2,554.23 FL	*- FL
13	1		*REAR LHS RIM	Not Necessary	968.72 FL	*- FL
14	1		*LHS SIDE MIRROR	Distorted	1,090.37 FL	*1,090.37 FL
15	1		*LHS SIDE MIRROR COVER	Cracked	406.54 FL	*406.54 FL
16	1		*LHS SIDE MIRROR GLASS	Cracked	292.22 FL	*292.22 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	13,770.25	6,908.17
- List Item Discount on L Items 5.00/10.00% (S\$)	688.51	690.82
Total Parts (S\$)	13,081.74	6,217.35

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE & INSTALL LHS BODY ATTACHMENTS & FITTINGS TO ENABLE REPAIRS: TO REPLACE DAMAGED PARTS AS LISTED ABOVE	New	2,000.00	600.00
2	TO SPRAY PAINTING ON: LHS FRONT FENDER, LHS FRONT DOOR, REAR LHS DOOR, REAR LHS FENDER, LHS SIDE SKIRT	New	1,500.00	1,000.00
3	WHEEL ALIGNMENT	New	120.00	60.00
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS	New	280.00	150.00
5	TO REMOVE & TRANSFER LHS FRONT & REAR DOOR TRIM BOARD, DOOR SCREEN POWER WINDOW & ELECTRICAL WIRINGS & SERVICEABLE FITTINGS TO NEW DOOR AND TEST FUNCTION	New	400.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,300.00</b>	<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >