



Your Ref : SNM22D209072/C01/TAYHP

Date: 06th Jan 2022

Our Ref : CS/CTI22012877/Gqy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMV 8576H
ACCIDENT ON 16/12/2022**

Instruction was received to inspect the vehicle Reg. No. SMV 8576H. The inspection was conducted on 27/12/2022 at the premises of M/s Auto Insure Pte Ltd, 6 Marsiling Lane, Singapore 739145.

The following vehicle information was recorded:

Registration Number	: SMV 8576H
Make/Model	: Toyota Voxy Hybrid 7-Seater 1.8X CVT
Year of Registration	: 2020
Body Colour	: Black
Chassis Number	: ZWR800436844
Engine Capacity	: 1797 cc

The vehicle sustained damages at the front, rear portion, o/s, n/s body, undercarriage and rooftop. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 180,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 54,151.00
Nett Liability	<u>S\$ 125,849.00</u> =====

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEE, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.