1/4/23, 8:48 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI22012878/UVY3M4
3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 Date: 04/01/2023

REFERENCE

Insured/Claimant: SITI MASKINAH BIN MUZAKIR Policy No: DMPCSNA00037662202

Date of Loss: 15/12/2022 Nature of Claim: OD Claim No: SNM22D209250/C01/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMQ1798G

Make & Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A) Engine No: 27492030837807

Reg. Date: 10/02/2017 (Man. Year: 2016) Chassis No: WDC2539462F160577

Colour: Black Odometer: 0 km

Engine Capacity: 1991 cc

Market Value/New Car

Price: S\$120,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Bridgestone 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|---------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total | al (S\$) 0.00 | 0.00 | 0.00 | |
| - Exces | o.00 | 1,250.00 | -1,250.00 | |
| Nett Amour | nt (S\$) 0.00 | -1.250.00 | 1.250.00 | |

INSPECTION

Date of Assignment: 27/12/2022 Present Location: Jin Auto Services Pte Ltd (Defu)

JIN AUTO SERVICES PTE LTD

Date Inspected: 27/12/2022 Inspected At: BLK 14 DEFU LANE 10

#01-412 SINGAPORE 539195

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$120,000.00 OMV : \$46,340.00 PARF Rebate (1): \$39,813.00 \$48,209.00 Quota Premium Paid: \$19,866.00 COE Rebate (2): Total Rebate (1) + (2) = : \$59,679.00

The total amount incurred will be Market Value \$120,000.00 minus Total Rebate \$59,679.00 = \$60,321.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

1/4/23, 8:48 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2023)

Parts: M1-SUV MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ1798G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

1/4/23, 8:48 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >