

Your Ref : SNM22D209250/C01

Date: 04th Jan 2023

Our Ref : CS/CTI22012878/Uvy3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMQ 1798G
ACCIDENT ON 15/12/2022**

Instruction was received to inspect the vehicle Reg. No. SMQ 1798G. The inspection was conducted on 27/12/2022 at the premises of M/s Jin Auto Services Pte Ltd, Blk 14 Defu Lane 10, #01-412, Singapore 539195.

The following vehicle information was recorded:

Registration Number	: SMQ 1798G
Make/Model	: Mercedes Benz GLC250 4Matic Auto
Year of Registration	: 2017
Body Colour	: Black
Chassis Number	: WDC2539462F160577
Engine Capacity	: 1991 cc

The vehicle sustained damages at the front n/s portion, n/s and o/s body. The undercarriage and chassis frame affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 120,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 59,679.00)
Nett Liability	<u>S\$ 60,321.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.