



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Attn: The Motor Claims Department

Date 30/12/2023

Your Insured Vehicle - SJW 1181 P

Allianz SE, Singapore Branch

79 Robinson Road, #09-01

Asia Square Tower 1

claims@allianz.com.sg

Singapore 068897

Dear Sir,

Estimated Cost of repair for Vehicle No ES 3223 U And SJW 1181 P on 24/12/2022 at 09:00am.

To Supply:-

Nett Item:

1pc	Front head lamp RH		\$3,030.00
1pc	Front fender RH		\$ 700.00
1pc	Front fender cowlding RH		\$ 208.00
1pc	Front bumper		\$1,400.00
1pc	Front bumper bracket		\$ 180.00
1pc	Fronr bumper side retainer RH		\$ 40.00
4pcs	Front bumper sensor	\$ 280.00	\$1,120.00
1pc	Fronr bumper under cover		\$ 340.00
1pc	Front sport rim RH		\$1,100.00
1pc	Front head lamp low beacket		\$ 30.00
			<u>\$8,148.00</u>
		Less	10% \$ 814.80
			<u>\$7,333.20</u>
	To dismanlte & replace damage parts,panel beat where necessary		\$ 520.00
	To putty,apply primer & spray paint on the affecte portion.		\$ 680.00
	Computer Wheel Alignment		\$ 120.00
	To check wiring functions.		\$ 80.00
			<u>\$8,733.20</u>



WDD 1173422N 489548

ES 3223U

front Head Lamp RH cut ✓ \$3030N
front fender RH Rip x \$700N
front fender cowling RH Deformed ✓ \$208N
front Bumper Distorted ✓ \$1400N
front Bumper Bracket, ? \$180N
front Bumper side Retainer RH Damaged ✓ \$40N
front Bumper sensor ? \$280N X 4
front Bumper under cover pen \$340N
front sport Rim RH cut — \$1100N
Head Lamp Lower Bracket ? \$30N
Knocking Labour ~~\$520~~ 400
spray painting ~~\$680~~ 400
Alignment ~~\$120~~ 80
wiring ~~\$80~~ 30

Adrian King,
A/S 30/12/22 04 Days