

Vehicle Damage Assessment Report for [SME8836Y]

Estimate Created: 27/12/2022 15:07 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/02/2023 15:40 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Kia	Model	Cerato
Engine Type			
License Plate Number	SME8836Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$700.00 with 2 days for repair

Insurlogic 5 (05/02/2023 15:39)

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED AREAS	RnR	200.00	0.00 %	200.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	500.00	0.00 %	500.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	200.00
		Paint Labor Subtotal	500.00
		Labor Subtotal	700.00

Summary

Repair Cost	700.00
Discount(0 %)	(0.00)
	700.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	700.00