



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2303474
3 ANSON ROAD #16-00	INV Date	01/06/2023
SPRINGLEAF TOWER	Reference	CC6/CTI22012888/Kya3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SMQ 3356K
Insured Veh.	SMS 8804R
Claim No.	SNM22D209391/C02
Policy No.	DMCVSNW00280592200
Accident Date	20/12/2022
Inspection Date	30/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22012888/Kya3q2 Date: 01/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMS 8804R	Veh. Inspected	SMQ 3356K
Policy No.	DMCVSNW00280592200	Coverage (\$)	0.00
Claim No.	SNM22D209391/C02	Excess (\$)	0.00
Assign From		Assign Date	30/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP72002614	Colour	METALLIC PEARL WHITE
Odometer	291855 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	GREENTRAC	8 mm
L/H Front Tyre	185/60 R15	GREENTRAC	8 mm
R/H Rear Tyre	185/60 R15	APLUS	6 mm
L/H Rear Tyre	185/60 R15	APLUS	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/12/2022	Inspection Date	30/12/2022
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3356K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,072.50	1,072.50
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	74.10	74.10
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	55.60	55.60
1	REAR TAILGATE 'SHUTTLE' EMBLEM	NECESSARY	74.10	74.10
1	REAR TAILGATE 'HYBRID' EMBLEM	NECESSARY	58.50	58.50
1	REAR TAILGATE MECHANISM LOCK	TO REPAIR SEE LABOUR	215.10	-
1	REAR TAILGATE INNER TRIM BOARD	MTG CRACKED	363.30	320.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	126.80	-
1	REAR BUMPER	BUCKLED	872.90	872.90
1	REAR BUMPER INNER BUZZER	SERVICEABLE	110.10	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	546.80	-
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	126.80	-
	LESS 20% DISCOUNT		-739.32	-505.54
			2,957.28	2,022.16
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	50.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR END PANEL JOINT SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			310.00	90.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST AT ACCIDENT AREAS .INCLUSIVE OF THE REPAIR OF REAR TAILGATE MECHANISM LOCK AND REAR END PANEL .		700.00	400.00
	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS .		700.00	440.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR WINDSCREEN GLASS & ETC.		120.00	120.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		80.00	15.00

Report Ref No. CC6/CTI22012888/Kya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE & UNDERSEAL MATERIALS.		80.00	30.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	NOT NECESSARY	80.00	-
			1,760.00	1,005.00
GRAND TOTAL			5,027.28	3,117.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC6/CTI22012888/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 3356K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 3356K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 3356K

RE-INSPECTION

