

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8082T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	503.04	503.04
1	REAR BUMPER LOWER COVER	CUT	654.96	654.96
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	378.32	-
1	REAR BUMPER TOW COVER	DEFORMED	82.70	82.70
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-410.26	-315.68
			1,230.76	947.02
<u>NETT ITEMS</u>				
1	BUMPER REVERSE SENSOR (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-5.00	-
			45.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.		550.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK WIRING & LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			970.00	630.00
GRAND TOTAL			2,367.89	1,749.15

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,400.00
---	--	--	-----------------

Report Ref No. NS/INC22012893/Tny3m4



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.